

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014221/QGA3Q2
Date: 18/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480163
Claimant Vehicle No :	SLC6353J	Insured Vehicle No :	SLG1197E
Date of Loss:	20/12/2020	Nature of Claim:	TP
		Claim No:	6515584894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC6353J		
Make & Model:	TOYOTA SIENTA, 1.5 X (A)	Engine No:	2NR8604623
Reg. Date:	20/05/2016 (Man. Year: 2016)	Chassis No:	NSP1707028196
Colour:	Blue	Odometer:	293470 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firena 6 mm	Rear Left Side:	Firena 6 mm
Front Right Side:	Firena 6 mm	Rear Right Side:	Firena 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,579.92	5,114.60	7,465.32	59.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,820.00	2,680.00	2,140.00	44.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,399.92	7,794.60	9,605.32	55.20
Approved Total (Overridden) (S\$)		6,250.00		

(S\$)	17,399.92	6,250.00	11,149.92	64.08
+ GST 7.00/7.00% (S\$)	1,217.99	437.50	780.49	64.08
Nett Amount (S\$)	18,617.91	6,687.50	11,930.41	64.08
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,139.50		

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020

Estimated Period of Repair: 7.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Crumpled	1,470.00 FL	*1,135.00 FL
2	1		*REAR TOP SPOILER	Serviceable	850.80 FL	*- FL
3	1		*REAR TAILGATE 3RD BRAKE LIGHT	Serviceable	280.00 FL	*- FL
4	1		*REAR TAILGATE WEATHERSTRIP	Crumpled	360.00 FL	*360.00 FL
5	1		*REAR TAILGATE LOCK ASSY WITH COUTERSY LAMP	Crumpled	504.00 FL	*399.10 FL
6	1		*REAR TAILGATE LOCK CATCH	Serviceable	64.80 FL	*- FL
7	1		*REAR TAILGATE RH UPPER HINGE	Serviceable	136.80 FL	*- FL
8	1		*REAR TAILGATE LH UPPER HINGE	Serviceable	136.80 FL	*- FL
9	1		*REAR TAILGATE LH DAMPER	Serviceable	352.80 FL	*- FL
10	1		*REAR TAILGATE RH DAMPER	Serviceable	352.80 FL	*- FL
11	1		*REAR TAILGATE BACK DOOR TRIMBOARD	Serviceable	580.00 FL	*- FL
12	1		*REAR TRAY LUGGAGE COMPARTMENT	Serviceable	420.00 FL	*- FL
13	1		*REAR SPARE TYRE COMPARTMENT BOX	Serviceable	400.00 FL	*- FL
14	1		*REAR SPARE TYRE PANEL	Repair	1,200.00 FL	*- FL
15	1		*REAR TAILGATE CENTER GARNISH HOLDER	Crumpled	342.00 FL	*342.00 FL
16	1		*REAR TAILGATE TOYOTA LOGO	Necessary	60.00 FL	*60.00 FL
17	1		*REAR LICENCE LAMP	Crumpled	120.00 FL	*120.00 FL
18	1		*R/R TAILLAMP	Serviceable	550.00 FL	*- FL
19	1		*R/L TAILLAMP	Crumpled	550.00 FL	*550.00 FL
20	1		*R/L TAILGATE REFLECTOR	Crumpled	380.00 FL	*380.00 FL
21	1		*R/R TAILGATE REFLECTOR	Serviceable	380.00 FL	*- FL
22	1		*REAR WIPER MOTOR	Serviceable	350.00 FL	*- FL
23	1		*REAR WIPER ARM	Serviceable	80.00 FL	*- FL
24	1		*REAR WIPER BLADE	Serviceable	35.00 FL	*- FL
25	1		*REAR END PANEL	Dented	828.00 FL	*650.00 FL
26	1		*REAR END PANEL LOWER	Serviceable	633.60 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Crumpled	250.00 FL	*165.80 FL
28	1		*REAR BUMPER COVER	Crumpled	1,080.00 FL	*788.00 FL
29	1		*REAR BUMPER LH SIDE BRACKET	Broken	105.00 FL	*105.00 FL
30	1		*REAR BUMPER RH SIDE BRACKET	Serviceable	105.00 FL	*- FL
31	1		*REAR BUMPER LH BRACKET	Serviceable	90.00 FL	*- FL
32	1		*REAR BUMPER RH BRACKET	Serviceable	90.00 FL	*- FL
33	1		*REAR BUMPER RH SUPPORT	Serviceable	88.05 FL	*- FL
34	1		*REAR BUMPER LH SUPPORT	Serviceable	88.05 FL	*- FL
35	1		*REAR BUMPER LH EXTENSION SIDE PAD	Serviceable	320.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER RH EXTENSION SIDE PAD	Serviceable	320.00 FL	*- FL
37	1		*REAR BUMPER CENTER BLACK PAD	Scratched	480.00 FL	*380.00 FL
38	1		*REAR BUMPER RH REFLECTOR	Serviceable	133.20 FL	*- FL
39	1		*REAR BUMPER RH REFLECTOR	Serviceable	133.20 FL	*- FL
40	1		*REAR BUMPER TOW COVER	Scratched	40.00 FL	*40.00 FL
41	1		*KEYLESS SMART BUZZER ANTENA	Serviceable	120.00 FL	*- FL
42	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
43	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS
44	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
45	1		*BODY SEALANT	Necessary	100.00 FS	*40.00 FS
46	1		*REAR NUMBER PLATE	Scratched	100.00 FS	*50.00 FS
47	1		*R/L FENDER OUTER GARNISH	Crumpled	480.00 FL	*322.90 FL
48	1		*R/L FENDER INNER GARNISH	Crumpled	580.00 FL	*515.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,559.90	6,692.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,979.98	1,578.20
Total Parts (\$\$)	12,579.92	5,114.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	120.00	120.00
2	TRANSFER TAILGATE MECHANISM	New	100.00	60.00
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR BUMPER END PANEL AND SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS ,ALSO INCLUDE STRAIGHTENNING OF BOTH REAR CHASSIS MEMBERS AND FLOOR PANEL	New	2,500.00	1,250.00
4	TO RESPRAY REAR TAILGATE ,REAR END PANEL,SPARE TYRE PANEL, REAR BUMPER ,ROOF TOP AND BOTH REAR FENDERS	New	1,800.00	1,200.00
5	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENTS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	50.00
Gross Labour Cost (S\$)			4,820.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >