Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014222/UVD3Q2

Date: 30/12/2020

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00057962004

Claimant Vehicle No:

SKX6308S

Insured Vehicle No:

YN8841S

Date of Loss: 17/12/2020 Nature of

Claim:

Claim SNM20D204948/C02/TANKL No:

CAXF18986

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX6308S**

VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A) Make & Model:

21/12/2015 (Man. Year: 2014)

Chassis No: WVWZZZ16ZFM002210 Odometer: 133185 km

Engine No:

Colour: Brown

Engine Capacity: Market Value/New Car

N/A

1390 cc

Price:

Reg. Date:

Market Value/New Car Price

Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17 225/45ZR17 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,232.57	3,810.77	14,421.80	79.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	990.00	4,560.00	82.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,782.57	4,800.77	18,981.80	79.81
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	23,782.57	3,800.00	19,982.57	84.02

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 24/12/2020 Inspected At: Euro Success Services Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 #02-03

AUTOBAY Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)		
Parts:	143	VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SKX6308S)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted/Torn	1,500.00 FL	*1,215.32 FL
2	1		*FRONT BUMPER TOWING COVER	Not Necessary	45.50 FL	*- FL
3	2		*FRONT R/H BUMPER BRACKET	Not Necessary	250.00 FL	*-FL
4	1		*FRONT GRILLE	Cracked	450.00 FL	*422.50 FL
5	1		*FRONT BUMPER EMBLEM	Not Necessary	125.00 FL	*- FL
6	1		*FRONT R/H DOOR	Repair	1,963.45 FL	*- FL
7	1		*FRONT R/H DOOR MIRROR	Not Necessary	896.50 FL	*- FL
8	2		*FRONT R/H DOOR HINGE	Not Necessary	171.60 FL	*- FL
9	1		*FRONT R/H HEADLAMP	Cracked	1,350.00 FL	*1,315.20 FL
10	1		*FRONT R/H HEADLAMP BRACKET	Not Necessary	125.00 FL	*- FL
11	1		*FRONT R/H FENDER	Badly Dented	800.33 FL	*621.32 FL
12	1		*FRONT R/H FENDER INNER SHIELD	Torn	249.69 FL	*215.40 FL
13	1		*FRONT R/H LOWER ARM	Not Necessary	699.79 FL	*-FL
14	1		*FRONT R/H KNUCKLE ARM	Not Necessary	1,388.70 FL	*- FL
15	1		*FRONT R/H KNUCKLE ARM ABS SENSOR	Not Necessary	1,400.70 FL	*-FL
16	1		*FRONT R/H KNUCKLE WHEEL BEARING	Not Necessary	600.97 FL	*-FL
17	1		*FRONT R/H DRY SUP	Not Necessary	1,750.00 FL	*- FL
18	2		*FRONT R/H UPPER ARM	Not Necessary	1,500.00 FL	*- FL
19	1		*FRONT TRIM ARM	Not Necessary	1,350.75 FL	*- FL
20	1		*FRONT ABSORBER MOUNTING HOUSING	Not Necessary	1,450.77 FL	*-FL
21	1		*FRONT R/H SHOCK ABSORBER	Not Necessary	1,300.77 FL	*-FL
22	1		*FRONT R/H SPORT RIM	Bent	500.00 FS	*400.00 FS
23	1		*FRONT R/H TYRE (CUT)	Not Consistent With The Impact	300.00 FS	*-FS
F=Fra	nchise	part. S=S	SpcNett. L=ListItemDisc.	•		
				Sub Total (S\$)	•	4,189.74
	- List Item Discount on L Items 10.00/10.00% (S\$)				1,936.95	378.97
				Total Parts (S\$)	18,232.57	3,810.77

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING (FOUR WHEEL)	New	250.00	0.00
2	TO CHECK WHEEL ALIGNMENT	New	200.00	60.00
3	TO REMOVE, REFIX FRONT AND REAR UNDERCARRIAGE	New	500.00	0.00
4	TO RESPRAY UNDERCOATING	New	550.00	30.00
5	TO RESPRAY PAINTING AND ETC	New	1,500.00	600.00
6	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	New	2,200.00	300.00
7	TO REMOVE,REFIX REAR GLASS AND REAR FENDER GLASS	New	350.00	0.00
	Gross Labour Cost (S\$)		5,550.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >