

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014223/UTD3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00047132000

Claimant Vehicle No : SMM3602X Insured Vehicle No : GBF1236A

Date of Loss: 18/12/2020 Nature of Claim: TP Claim No: SNM20D204949/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM3602X

Make & Model: LEXUS RX, 3.5 450h Hybrid (A) Engine No: 2GRJ490427

Reg. Date: 14/11/2011 (Man. Year: 2011) Chassis No: JTJBC11A302427736

Colour: Black Odometer: 67735 km

Engine Capacity: 3456 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,443.98	2,570.33	17,873.65	87.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	1,430.00	3,370.00	70.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,243.98	4,000.33	21,243.65	84.15
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	25,243.98	3,200.00	22,043.98	87.32

INSPECTION

Date of Assignment: 12/01/2021

Date Inspected: 06/01/2021 Inspected At: Euro Success Services Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 #02-03
AUTOBAY
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)
Parts:	M1-SUV	LEXUS RX 3.5 450h Hybrid (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM3602X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Not Necessary	3,750.00 FL	*- FL
2	1		*REAR TAILGATE GLASS MOULDING	Not Necessary	345.00 FL	*- FL
3	1		*REAR TAILGATE INNER LOCK	Not Necessary	740.00 FL	*- FL
4	1		*REAR TAILGATE STRIKER LOCK	Not Necessary	250.60 FL	*- FL
5	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	250.30 FL	*- FL
6	1		*REAR TAILGATE EMBLEM	Not Necessary	78.80 FL	*- FL
7	1		*REAR TAILGATE HARRIER EMBLEM	Not Necessary	68.80 FL	*- FL
8	1		*REAR TAILGATE RX450H EMBLEM	Not Necessary	68.90 FL	*- FL
9	2		*REAR L-R TAILGATE LAMP	Not Necessary	3,500.00 FL	*- FL
10	2		*REAR L-R TAILLAMP	Not Necessary	3,300.00 FL	*- FL
11	1		*REAR TAILGATE INNER BOARD	Not Necessary	1,850.00 FL	*- FL
12	1		*REAR TAILGATE RUBBER	Not Necessary	250.00 FL	*- FL
13	1		*REAR END PANEL	Dented	1,150.00 FL	*688.10 FL
14	1		*REAR END PANEL INNER BOARD	Not Necessary	927.60 FL	*- FL
15	1		*REAR END PANEL SENSOR SWITCH	Not Necessary	268.00 FL	*- FL
16	1		*REAR BUMPER	Dented/Deformed	2,300.00 FL	*955.10 FL
17	1		*REAR BUMPER SPONGE	Cracked	375.00 FL	*188.20 FL
18	1		*REAR BUMPER REINFORCEMENT	Dented	900.00 FL	*752.30 FL
19	1		*REAR BUMPER REINFORCEMENT LOWER PAD KIT	Not fitted	980.00 FL	*- FL
20	2		*REAR L-R BUMPER RETAINER	Not Necessary	179.20 FL	*- FL
21	1		*SET REAR BUMPER SENSOR	Shorted	800.00 FS	*200.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
23	1		*SET REAR TAILGATE INNER BOARD CLIP	Not Necessary	45.00 FS	*- FS
24	1		*SET REAR END PANEL INNER BOARD CLIP	Not Necessary	45.00 FS	*- FS
25	1		*REAR TAILGATE GLASS SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*REAR NUMBER PLATE WITH BOX	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,597.20	2,828.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,153.22	258.37
Total Parts (\$\$)	20,443.98	2,570.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	200.00	0.00
2	TO APPLY UNDERCOATING ON ACCIDENT AFFECTED PARTS	New	350.00	30.00
3	TO TRANSFER REAR TAILGATE MECHANISM TO FACILITATE REPAIR	New	150.00	0.00
4	TO DISMENTLE & REPLACING REVERSE SENSOR	New	100.00	50.00
5	TO PROVIDE LABOUR,WORKMANSHIP TO DISMENTLE THE ABOVE MENTIONED PARTS INCLUDE OF CUT,WELD AND RE ALIGN BODY STRUCTURE AND DAMAGE PARTS CAUSED BY THE ACCIDENT	New	2,000.00	700.00
6	TO RESPRAY PAINT ON ACCIDENT AFFECTED PARTS	New	2,000.00	650.00
Gross Labour Cost (S\$)			4,800.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >