



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD	Cust No/Name LC000162/ CYCLE & CARRIAGE LEASING PTE L
239 ALEXANDRA ROAD	Reg No/Reg Date SMP5948U / 01/10/201
SINGAPORE 159930	Date In/Mileage / 0
Contact No Mobile: 85188668	Chassis No KNAF1416MK5050457
	Engine No G4FGKH745341
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	18/12/2020/ 13:19	QUE	261 / Edwin Caina	25976

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER REPAIR RR END PNL				640 2560.00
E PNT98000 RESPRAY RR BUMPER & RR END PNL				550 1100.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET				1 X 320.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				280.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				120.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				100.00
M SUNDRY SUPPLY REVERSE SENSOR				8 X 280.00
M SUNDRY Sundries				20 50.00
M COVER-RR BUMPER / BR	1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR / BR	1.00	241.00	00.00	241.00
M COVER-RR BUMPER FOG LAMP, LH / CUT	1.00	19.00	00.00	19.00
M LAMP ASSY-SIDE T/SIGNAL, LH / ? X NM	1.00	181.00	00.00	181.00
M BEAM-RR BUMPER / BR (photo) ? X NM	1.00	318.00	00.00	318.00
M BRACKET ASSY-RR BPR SIDE UPR, L / ? X NM	1.00	25.00	00.00	25.00
M STAY-RR BUMPER LH / BT	1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH / BT	1.00	65.00	00.00	65.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 22/12/20, 1:30pm

Confirm & accepted by

DATE: WKL MCL

REMARKS: PIP

7% GST on

Nett

6425.00

6,425.00

449.75

Total Payable

6,874.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.