

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014235/R1BA3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHD8591S	Insured Vehicle No :	SHD3454M
Date of Loss: 21/12/2020	Nature of Claim: TP	Claim No: MCT20120384

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD8591S		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDEU461323
Reg. Date:	15/09/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU093794
Colour:	Yellow	Odometer:	794013 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,277.90	4,336.91	2,940.99	40.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,470.00	1,770.00	54.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,517.90	5,806.91	4,710.99	44.79
Approved Total (Overridden) (S\$)		4,650.00		
(S\$)	10,517.90	4,650.00	5,867.90	55.79
+ GST 7.00/7.00% (S\$)	736.25	325.50	410.75	55.79
Nett Amount (S\$)	11,254.15	4,975.50	6,278.65	55.79
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$103.43/day) (S\$)		310.29		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,413.24		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 22/12/2020 Inspected At:

Ding Automotive Pte Ltd (SIN MING)
BLK 10 #01-20 SIN MING, IND EST

SEC C
Singapore 575645

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD8591S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FRONT BUMPER	Cracked	599.68 FL	*599.68 FL
3	1		*FRONT BUMPER TOP SEAL	Necessary	36.20 FL	*36.20 FL
4	1		*FRONT BUMPER LOWER LIP	Distorted	83.87 FL	*83.87 FL
5	1		*FRONT BUMPER AIR DUCT LH	Not Necessary	105.63 FL	*- FL
6	1		*FRONT BUMPER RETAINER LH	Cracked	48.32 FL	*48.32 FL
7	1		*FRONT BUMPER RETAINER RH	Not Necessary	48.32 FL	*- FL
8	1		*FRONT BUMPER RADIATOR GRILLE	Scratched	1,110.10 FL	*1,110.10 FL
9	1		*FRONT FENDER LH	Bent	659.50 FL	*659.50 FL
10	1		*FRONT FENDER INNER SHIED LH	Not Necessary	205.12 FL	*- FL
11	1		*HEADLAMP LH	Cracked	1,808.10 FL	*1,808.10 FL
12	1		*BONNET	Repair	1,812.68 FL	*- FL
13	1		*BONNET HINGE LH	Not Necessary	61.85 FL	*- FL
14	1		*FRONT WHEEL CAP LH	Not Necessary	265.50 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Cracked	962.87 FL	*962.87 FL
16	1		*SIDE SKIRT LH	Not Necessary	695.88 FL	*- FL
17	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
18	1		*FRONT FENDER INNER SHIELD CLIP SET LH	Not Necessary	35.00 FS	*- FS
19	1		*REPAIR FRONT WHEEL HOUSE PANEL LH (NPA)	Not Necessary	0.00 FS	*- FS
20	1		*FRONT TYRE LH	Not Necessary	280.00 FS	*- FS
21	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,978.62	5,398.64
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,700.72	1,061.73
Total Parts (\$\$)	7,277.90	4,336.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREA	New	1,000.00	600.00
2	RUST PROOFING	New	80.00	40.00
3	DIAGNOSTIC (CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	New	180.00	60.00
4	ADJUST HEADLAMP AIM	New	80.00	30.00
5	R&R RADIATOR & CONDENSER & TURBO INTERCOOLER	New	180.00	80.00
6	VACUUM & TOP UP AIR COND GAS R-134A	New	150.00	60.00
7	R&R FRONT RIM & TYRE LH	New	120.00	0.00
8	CONDUCT 4 WHEEL ALIGNMENT & BALANCING	New	150.00	0.00
9	RESPRAY FRONT BUMPER	New	250.00	200.00
10	RESPRAY FRONT FENDER LH	New	250.00	200.00
11	RESPRAY BONNET & BONNET HINGE LH	New	300.00	200.00
12	RESPRAY SIDE SKIRT LH	New	250.00	0.00
13	RESPRAY FRONT WHEELHOUSE PANEL LH	New	250.00	0.00
Gross Labour Cost (S\$)			3,240.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >