

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014239/ETD3E2

Date: 26/01/2021

REFERENCE

Insured/Claimant:	YANG CHIA CHIANG,BARRY	Policy No:	1900258752	
Date of Loss:	21/12/2020	Nature of Claim:	OD	Claim No: 3672957524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR4113H	Engine No:	G4FGKH739355
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416ML5060029
Reg. Date:	03/01/2020 (Man. Year: 2019)	Odometer:	9633 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 4 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,053.62	2,161.60	1,892.02	46.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	2,870.00	1,940.00	40.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,863.62	5,031.60	3,832.02	43.23
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,563.62	4,731.60	3,832.02	44.75
+ GST 7.00/7.00% (S\$)	599.45	331.21	268.24	44.75
Nett Amount (S\$)	9,163.07	5,062.81	4,100.26	44.75

INSPECTION

Date of Assignment:	22/12/2020	
Date Inspected:	22/12/2020	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL
4	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
5	1		*HINGE ASSY-HOOD, LH	Not Necessary	43.00 FL	*- FL
6	1		*HINGE ASSY-HOOD, RH	Not Necessary	43.00 FL	*- FL
7	1		*PANEL-FENDER, LH	Repair	430.00 FL	*- FL
8	1		*LAMP ASSY-HEAD, LH	Cut	1,219.00 FL	*1,219.00 FL
9	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	303.00 FL	*- FL
10	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
12	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
13	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
14	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
15	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	14.00 FL	*- FL
16	1		*LAMP ASSY-SIDE REPEATER, LH	Cut	143.00 FL	*143.00 FL
17	1		*MOULDING-FRONT BUMPER, LH	Cut	36.00 FL	*36.00 FL
18	2		*RETAINER-BUMPER SIDE MTG	Necessary	2.00 FL	*2.00 FL
19	1		*GRILLE ASSY-RADIATOR	Cut	328.00 FL	*328.00 FL
20	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
21	1		*GRILLE-FRONT BUMPER	Broken	262.00 FL	*262.00 FL
22	1		*COVER-FR BUMPER FOG LAMP, LH	Not Necessary	15.00 FL	*- FL
23	1		*COOLANT (4L)	Not Necessary	26.00 FN	*- FN
					Sub Total (\$\$)	5,043.002,697.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	983.40535.40
					- Nett Item Discount on N Items 23.00/23.00% (\$\$)	5.980.00
					Total Parts (\$\$)	4,053.622,161.60

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER, LH FRONT FENDER, REPAIR FRONT BONNET. REPAIR RH FRONT FENDER	New	2,000.00	800.00
2	REMOVE AND INSTALL RADIATOR AND A/C CONDENSER TO FACILITATE REPAIR WORK	New	100.00	0.00
3	TOP UP A/CON GAS AND CHECK A/CON SYSTEM	New	80.00	0.00
4	PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER AND AFFECTED PORTION. CLEAR COAT	New	2,400.00	1,920.00
5	PERFORM RUST PREVENTION	New	80.00	0.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (S\$)			4,810.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >