



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/YANG CHIA CHIANG, BARRY
	Reg No/Reg Date	SMR4113H / 03/01/202
	Date In/Mileage	/ 9633
	Chassis No	KNAF3416ML5060029
	Engine No	G4FGKH739355
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/12/2020/ 16:33	QUD	247 / DonBong	26112			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER, LH FRONT FENDER, REPAIR FRONT BONNET, 40x2 REPAIR RH FRONT FENDER								800
E PNT88000								100.00
REMOVE AND INSTALL RADIATOR AND A/C CONDENSER TO FACILITATE REPAIR WORK								?
M SUNDRY								80.00
TOP UP A/CON GAS AND CHECK A/CON SYSTEM								
E PNT98000								2400.00
PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, 480x4 (CR5 color) LH FRONT FENDER AND AFFECTED PORTION CLEAR COAT								1920
M SUNDRY								80.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								50.00
SUPPLY FRONT NUMBER PLATE WITH FRAME								
M SUNDRY								50.00
SUNDRIES								
M	CARRIER ASSY-FRONT END MODULE				1.00	675.00	20.00	540.00
M	BEAM COMPLETE-FR BUMPER				1.00	497.00	20.00	397.60
M	HINGE ASSY-HOOD, LH				1.00	43.00	20.00	34.40
M	HINGE ASSY-HOOD, RH				1.00	43.00	20.00	34.40
M	PANEL-FENDER, LH				1.00	430.00	20.00	344.00
M	LAMP ASSY-HEAD, LH				1.00	1219.00	20.00	975.20
M	LAMP ASSY-FRONT FOG, LH				1.00	303.00	20.00	242.40
M	ORNAMENT-KIA NO.115				1.00	32.00	20.00	25.60
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /YANG CHIA CHIANG, BARRY Reg No/Reg Date SMR4113H / 03/01/202 Date In/Mileage / 9633 Chassis No KNAF3416ML5060029 Engine No G4FGKH739355 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/12/2020/ 16:33	QUO	247 / DonBong	26112			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M	STIFFNER-FR BPR LWR				1.00	114.00	20.00	91.20
M	ABSORBER-FRONT BUMPER ENERGY				1.00	84.00	20.00	67.20
M	AIR DUCT-FR BUMPER, LH				1.00	14.00	20.00	11.20
M	LAMP ASSY-SIDE REPEATER, LH				1.00	143.00	20.00	114.40
M	MOULDING-FRONT BUMPER, LH				1.00	36.00	20.00	28.80
M	RETAINER-BUMPER SIDE MTG				2.00	1.00	20.00	1.60
M	GRILLE ASSY-RADIATOR				1.00	328.00	20.00	262.40
M	COVER-FR BUMPER				1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER				1.00	262.00	20.00	209.60
M	COVER-FR BUMPER FOG LAMP, LH				1.00	15.00	20.00	12.00
M	COOLANT (4L)				1.00	26.00	23.00	20.02

Estimate

22/12/20

SURVEYOR NAME: Steve CLKK) OD-NM ALL

SURVEYOR SIGNATURE: Excess - ?

DATE: P/P

REMARKS: By Bel sy 5 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed

Confirm & accepted by repairer. Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

7% GST on 8863.62  
Total Payable 9,484.07

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.