

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014240/KTF3Q2

Date: 03/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00105112002
Claimant Vehicle No :	SMM4972X	Insured Vehicle No :	XE4526M
Date of Loss:	08/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204765/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4972X	Engine No:	G4FGKU146835
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU910305
Reg. Date:	01/07/2019 (Man. Year: 2019)	Odometer:	16779 km
Colour:	Metallic Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,532.72	1,354.56	178.16	11.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	510.00	500.00	49.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,542.72	1,864.56	678.16	26.67
+ GST 7.00/7.00% (\$\$)	177.99	130.52	47.47	26.67
Nett Amount (\$\$)	2,720.71	1,995.08	725.63	26.67

INSPECTION

Date of Assignment:	29/12/2020	Inspected At:	Spark Car Care @ Braddell (HQ)
Date Inspected:	22/12/2020		205 BRADDELL RD
			Singapore 579701
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM4972X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled/Dented	474.40 FL	*474.40 FL
2	1		*FRONT BUMPER FOG LAMP RH	Serviceable	164.80 FL	*- FL
3	1		*FRONT BUMPER GRILLE RH	Serviceable	33.60 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	13.70 FL	*- FL
5	1		*FRONT BUMPER UPPER BRACKET RH	Repair	10.60 FL	*- FL
6	10		*FRONT BUMPER CLIP	Necessary	20.00 FL	*20.00 FL
7	1		*RH HEADLAMP	Cut	1,198.80 FL	*1,198.80 FL
					Sub Total (S\$)	1,915.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	383.18
					Total Parts (S\$)	1,532.72
						1,354.56

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE RH FRONT FENDER AND REPLACE DAMAGED PARTS	New	420.00	240.00
2	TO CHECK WIRING FUNCTIONS AND FOCUS HEADLAMPS	New	40.00	20.00
3	TO PUTTY,APPLY PRIMER & SPRAY-PAINT THE RH FRONT FENDER,FRONT BUMPER AND AFFECTED AREAS	New	500.00	250.00
4	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	50.00	0.00
Gross Labour Cost (\$\$)			1,010.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >