



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /LIM EILYN Reg No/Reg Date SMS33765 / 21/02/202 Date In/Mileage / 0 Chassis No MMBXTA03ALH000277 Engine No 3A92UJB8609 Make/Model MIT/20MY SPACE STAR 1.2 CVT 2WD Colour/Trim P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	21/12/2020/ 16:56	QUE	261 / Edwin Caina	61018				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000								2250.00	
RENEW FRT BUMPER & BONNET									
REPAIR LHF FENDER & FRT SUPPORT PNL									
E PNT98000								1400.00	
RESPRAY FRT BUMPER, BONNET, LHF FENDER & FRT SUPPORT PNL									
A 54900099								30.00	
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM									
A 10028901								120.00	
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST									
USING HI-SCAN PRO TEST									
M SUNDRY								80.00	
APPLY ANTI CORROSION ON AFFECTED AREAS									
M SUNDRY								50.00	
SUPPLY FRT NUMBER PLATE WITH CASING									
M SUNDRY								30.00	
Sundries									
M FACE, FR BUMPER					1.00	751	747.00	23.00	575.19
M CLIP, FR BUMPER					5.00		4.00	23.00	15.40
M BRACKET, FR BUMPER SIDE, LH					1.00		7.00	23.00	5.39
M GRILLE ASSY, RADIATOR					1.00		404.00	23.00	311.08
M MARK, THREE-DIA					1.00		69.00	23.00	53.13
M GARNISH, FR BUMPER SIDE, LH					1.00		173.00	23.00	133.21
M GARNISH, FR BUMPER, CTR					1.00		190.00	23.00	146.30
M GARNISH, FR BUMPER, LH					1.00		53.00	23.00	40.81
M HOOD					1.00		615.00	23.00	473.55
M CLIP, HOOD INSULATOR					8.00		3.00	23.00	18.48
M HEADLAMP ASSY, LH					1.00	1842	1832.00	23.00	1410.64
M BODY KIT, SPACE STAR, A66					1.00		1776.00	20.00	1420.80
M REINFORCEMENT, FR BUMPER					1.00		432.00	23.00	332.64

Estimate

675
 700
 70
 25/3/21, 4:00pm
 Steve CLKK) 00-N/A AL

Estimate

25/3/21, 4:00pm
Steve (LKK) 00-N/A A L

SURVEYOR NAME:

Confirm & accepted by

SURVEYOR SIGNATURE:

DATE:

REMARKS

Authorized signatory and company stamp

Nett 8,896.62
7% GST on 8896.62 622.76
Total Payable 9,519.38

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts needed are subject to confirmation

No validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.