

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014243/ETD3E2

Date: 26/01/2021

REFERENCE

Insured/Claimant:	GOH KOK SUA	Policy No:	2100490356		
Date of Loss:	20/12/2020	Nature of Claim:	OD	Claim No:	9250991469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH7433D		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGGH637993
Reg. Date:	17/11/2016 (Man. Year: 2016)	Chassis No:	KNAFZ411MH5648996
Colour:	Silver	Odometer:	50391 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,537.20	7,038.00	4,499.20	39.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,320.00	6,595.00	4,725.00	41.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,857.20	13,633.00	9,224.20	40.36
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	22,857.20	11,000.00	11,857.20	51.88
+ GST 7.00/7.00% (S\$)	1,600.00	770.00	830.00	51.88
Nett Amount (S\$)	24,457.20	11,770.00	12,687.20	51.88

INSPECTION

Date of Assignment:	22/12/2020		
Date Inspected:	22/12/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	16.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME		50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*GRILLE ASSY-RADIATOR	Cut	328.00 FL	*328.00 FL
4	1		*COVER-FR BUMPER	Repair	633.00 FL	*- FL
5	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	18.00 FL	*18.00 FL
6	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	91.00 FL	*91.00 FL
7	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
8	1		*RAIL ASSY-FR BUMPER	Not Necessary	496.00 FL	*- FL
9	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	177.00 FL	*- FL
10	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
11	1		*LOGO ASSY-KIA SUB	Necessary	37.00 FL	*37.00 FL
12	1		*EMBLEM-CERATO	Necessary	35.00 FL	*35.00 FL
13	1		*COVER-RR BUMPER	Broken	688.00 FL	*688.00 FL
14	1		*COVER-RR BUMPER, CTR	Broken	315.00 FL	*315.00 FL
15	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	69.00 FL	*- FL
16	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
17	1		*BRACKET-RR BEAM LWR, CTR	Bent	5.00 FL	*5.00 FL
18	1		*BRACKET-RR BEAM UPR MTG	Broken	3.00 FL	*3.00 FL
19	1		*BRACKET-RR BEAM UPR MTG, RH	Broken	3.00 FL	*3.00 FL
20	1		*STAY-RR BUMPER LH	Bent	120.00 FL	*120.00 FL
21	1		*STAY-RR BUMPER RH	Bent	120.00 FL	*120.00 FL
22	1		*BRACKET-RR BUMPER SIDE MTG, LH	Bent	29.00 FL	*29.00 FL
23	1		*BRACKET-RR BUMPER SIDE MTG, RH	Bent	29.00 FL	*29.00 FL
24	1		*GUARD-BUMPER REAR, RH	Missing	17.00 FL	*17.00 FL
25	1		*WIRING HARNESS-BWS EXT	Torn	216.00 FL	*216.00 FL
26	1		*ULTRASONIC SENSOR ASSY-P.A.S	Broken	177.00 FL	*177.00 FL
27	1		*ULTRASONIC SENSOR ASSY-P.A.S	Broken	177.00 FL	*177.00 FL
28	1		*ULTRASONIC SENSOR ASSY-P.A.S	Broken	177.00 FL	*177.00 FL
29	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	177.00 FL	*- FL
30	1		*PANEL ASSY-TRUNK LID	Dented	1,365.00 FL	*1,365.00 FL
31	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	68.00 FL	*- FL
32	1		*HINGE ASSY-TRUNK LID, RH	Not Necessary	68.00 FL	*- FL
33	1		*PANEL ASSY-RR COMB LAMP HSG, LH	Bent	166.00 FL	*166.00 FL
34	1		*PANEL ASSY-RR COMB LAMP HSG, RH	Not Necessary	166.00 FL	*- FL
35	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
36	1		*PNL ASSY-RR FLOOR RR COMPLETE	Dented	602.00 FL	*602.00 FL
37	1		*TRIM-TRANSVERSE RR	Broken	58.00 FL	*58.00 FL
38	1		*TRIM ASSY-LUGGAGE SIDE RH	Not Necessary	161.00 FL	*- FL
39	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	159.00 FL	*- FL
40	1		*TRIM ASSY-LUGGAGE SIDE LH	Not Necessary	161.00 FL	*- FL
41	1		*LAMP ASSY-REAR COMB INSIDE, RH	Not Necessary	710.00 FL	*- FL
42	1		*LAMP ASSY-REAR COMB INSIDE, LH	Cut	710.00 FL	*710.00 FL
43	1		*LAMP ASSY-REAR COMBINATION, RH	Not Necessary	788.00 FL	*- FL
44	1		*LAMP ASSY-REAR COMBINATION, LH	Cut	788.00 FL	*788.00 FL
45	1		*LAMP ASSY-HEAD, RH	Broken	1,707.00 FL	*1,707.00 FL
46	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,707.00 FL	*- FL
47	1		*C & C LOGO	Necessary	40.00 FS	*40.00 FS
48	1		*BRACKET-RR BEAM LWR MTG	Bent	5.00 FL	*5.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,394.00	8,770.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,856.80	1,732.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	11,537.20
						7,038.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT SUPPORT PANEL	New	800.00	400.00
2	SPRAY PAINT FOR FRT BUMPER	New	350.00	350.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	RENEW REAR BUMPER, BOOTLID, REAR LAMP HOUSING RH & LH, REAR END PANEL, REAR COMPARTMENT, REPAIR REAR CHASSIS RH & LH, REAR FENDER RH	New	5,600.00	2,800.00
6	REMOVE & INSTALL REAR SEATS AND CARPET	New	200.00	200.00
7	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	200.00	200.00
8	SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, REAR LAMP HOUSING RH & LH, REAR FENDER RH, REAR COMPARTMENT, REAR CHASSIS RH & LH	New	2,800.00	2,275.00
9	CONDUCT CELLEBENCH TO STRAIGHTEN REAR CHASSIS (* Check)	New	1,000.00	0.00
10	REMOVE & INSTALL FRT PARKING SENSOR	New	60.00	60.00
11	REMOVE & INSTALL REAR PARKING SENSOR	New	60.00	60.00
12	APPLY SEALANT FOR ACCIDENT PORTION	New	100.00	100.00
Gross Labour Cost (S\$)			11,320.00	6,595.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >