

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K	ESTIMATE	GST Reg No : MR-8500111-X			
Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No Make/Model	/GOH KOK SUA SLH7433D / 17/11/201			

ccount No	Terms	Date/Time Printed	CSE	Operator	· Andrews	WIP No		
AX00000	Credit			442 / CocoLu		26105		
AAUUUUU	Credit	Description of Good	ds / Services		Qty	Unit Price	Disc%	Amount
PNT88000	1	Description of Sec	T.T					400 800.
RENEW FR	T BUMPER,	FRT SUPPORT PANEL					ľ	790 350.
PNT98000	INT FOR F	RT BUMPER,						
SUNDRY	INI TOK I	KT DOM EK,					0	UT 50.
	ER PLATE	WITH FRAME					T	30.
90000001								50.
CHECK WI	RING & EL	ECTRICAL SYSTEM					- 1	120.
10028901		WASTER OUTCK HOTHC	LIT CCAN DDO	TECT			1	
		NOSTIC CHECK USING	mi-scan Pro	11231				
USING HI- PNT88000	-SCAN PRO	IESI ,	A 25 5	TOO A	45			5600.
DENEW DEA	R BUMPER	BOOTLID, REAR LAM	R HOUSING RH	REAR END P	ANEL (=	420 X 7		2800
REAR COMP	ARTMENT.	REPAIR REAR CHASSI	S RH & LH, I	EAR FENDER RH		フ	٠,,	
PNT88000		•	- 1/2				(photo)) 200.
REMOVE &	INSTALL F	REAR SEATS AND CARP	ET					200
PNT88000							Cphili	200
	INSTALL R	REAR COMPARTMENT TR	1M2	1/1				2800
NT98000	NT FOR RE	AR BUMPER, REAR EN	D DANEL DEA	R LAMP HOUSING BAT	& LH·	350X 6.5		2175
SPRAT PAI	NI FUK KE	AR COMPARTMENT, RE	AR CHASSIS R	H & LH		77° × 0.1		-
NT88000	ILH	AR COM ARTHERT, RE		~ 1		-		X 1000.
	ELLEBENCH	TO STRAIGHTEN REA	R CHASSIS				3 N	
NT88000								60.
REMOVE &	INSTALL F	RT PARKING SENSOR						60.
000887 <i>n</i>							- 1	
	INSTALL R	EAR PARKING SENSOR					- 1	40.
SUNDRY								
C&C LOGO SUNDRY								100.
	LANT FOR	ACCIDNET PORTION						
SUNDRY	LI,III I OK	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						20.
Sundry								
onfirm & ac	ccepted by							

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	/GOH KOK SUA 7433D / 17/11/201			
Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16	Reg No/Reg Date SLH7 Date In/Mileage Chassis No KNAF	/ 0 FZ411MH5648996			
AIG BUILDING	Engine No G4FG	GGH637993			
SINGAPORE 079120 Contact No 64191000	//ans///as	/FORTE K3 1.6 A SX HADQ SILKY SILVER / WK SATURN BLACK			

		Date (Time Brinted	CSE	Operator		WIP No		a program in the state of the
Account No	Terms	Date/Time Printed	JUL	442 / CocoLu		26105		
LAX00000	Credit	22/12/2020/ 08:41	- / Sarvices		Qty l	Init Price	Disc%	Amount
		Description of Goods	S / Sel Vices		1.00	328.00	20.00	262.40
M GRILLE A	SSY-RADIA	ATOR / CVI			1.00	633.00	20.00	506.40
M COVER-FR	BUMPER	X K	? £	0.0	1.00	18.00	20.00	14.40
M MOULDING	-FRT BPR	LICENSE PLATE	(k y/L) /	~ <i>13K</i>	1.00		20.00	72.8
M MOULDING	-FRONT BU	IMPER A/INTAKE (1º IMPER ENERGY 1 ⊀ Å	IN g. J		1.00		20.00	67.2
M ABSORBER	FRONT BU	IMPER ENERGY	390 C		1.00	496.00		396.8
M RAIL ASS	-FR BUMP		Λĺ		1.00	177.00		141.6
M ULTRASON	C SENSOR	H331 1 1/200 2			1.00		20.00	25.6
M ORNAMENT-	KIA NU.1	15 pc			1.00		20.00	29.0
LOGO ASSY	-KIY 20R				1.00	35.00		28.0
1 EMBLEM-CE		NC BR of		I	-1.00	688.00	20.00	550.
COVER-RR	BUMPER		\sim $^{\prime}$ $^{\prime}$	ma	25 2.00		20.00	252.
COVER-RR	BUMPER, C	TKEY 1 X AM	271	$ \cap \cap =$	2 1 1.00	69.00		55.
ANTENNA A		IKEY OF - PLANE	\mathcal{D}) \mathcal{L}	(<	2114.00-7	318.00		254.
BEAM-RR B	UMPER /	OR LATE			1.00	5.00		4.
BRACKET-R	R BEAM L	WR MIG			1.00	5.00		4.
BRACKET-R	R BEAM L	WR,CIR / OR			1.00	3.00	20.00	2.
BRACKET-R	R BEAM U				1.00	3.00	20.00	2.
BRACKET-R	R BEAM U	77-			1.00	120.00		96.
STAY-RR B					1.00	120.00		96.
STAY-RR B	UMPER RH	/ 01 12 /	- RT		1.00	29.00		23.
BRACKET-R	R BUMPER	SIDE MTG, LH	-RT		1.00	29.00	1/	23.
BRACKET-R	R BUMPER	SIDE MTG, RH			1.00	17.00		13.
GUARD-BUM	PER REAR	,RH / MIJ			1.00	216.00		172.
WIRING HA	RNESS-BW	S EXT / TAI			1.00	177.00		141.
ULTRASONI	C SENSOR	ASS1-P.A.S 2 36	' '		1.00	177.00		141.
ULTRASONI	C SENSOR	ASSY-P.A.S			1.00		20.00	141.
ULTRASON!	C SENSOR	ASSY-P.A.S	MM		1.00	177.00		141.
ULTRASON	C SENSOR	ASSY-P.A.S	1919		1.00	1365.00		1092.
1 PANEL ASS	Y-TRUNK	LID / VU			1.00	68.00		54.
HINGE ASS	SY-TRUNK	LID, LH 3 X X X		006 16)	1.00	68.00		54.4
M HINGE AS	SY-TRUNK	LID, RH	Q1	(phito)	1.00	166.00		132.8
M PANEL AS	SY-RR COM	18 LAMP HSG, LH		• 1000 T	1.00		20.00	132.8
M PANEL AS	SY-RR COI	1B LAMP HSG,RH ≺	MN		1.00			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen. Page 2 of 3



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

		do no		
Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/GOH KOK SUA		
Ltd.	Reg No/Reg Date	SLH74330 / 17/11/201		
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0		
78 SHENTON WAY #08-16	Chassis No	KNAFZ411MH5648996		
AIG BUILDING	Engine No	G4FGGH637993		
SINGAPORE 079120 Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A SX HADQ		
04131000	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
AX00000	Credit	22/12/2020/ 08:41		442 / CocoLu		26105		
		Description of Goods	/ Services		Qty	Unit Price		Amount
M TRIM-TRAM M TRIM ASSY M MAT ASSY M TRIM ASSY M LAMP ASSY M LAMP ASSY M LAMP ASSY	RR FLOOR ISVERSE R -LUGGAGE -LUGGAGE -REAR CO -REAR CO -REAR CO -REAR CO -HEAD,RH	RR COMPLETE RR COMPLETE COVERING X MM SIDE LH X MM MB INSIDE, RH X M M MB INSIDE, LH X MM MBINATION, RH X MM MBINATION, LH X MM MBINATION, LH X MM	1 1	imna	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	58.00 161.00 159.00 161.00 710.00 788.00 788.00	20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00	259.2 481.0 46.4 128.3 127.2 128.3 568.0 630.0 630.1 1365.1
			<u>ي</u> ا لي (ح			7		
LKK Auto Con the Repairer (• To resurvey be	sultants he	wing. ay painting		NM Autl				
 To display dam Parts prices ar Third party sur No illegal mod 	laged part(s) re subject to c rvey is on a "V Mication(s) is	onfirmation Vithout Prejudice" basis			7% GST on	Net*		22,857.2 1600.0
Acknowledged	by Repairer							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 3 of 3