

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1992U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PRIG4 COVER FRONT BUMPER	TORN	499.90	499.90
10	PRIVC BUMPER PIECE	NECESSARY	22.00	22.00
1	PRIG4 SUPPORT FRONT BUMPE	DEFORMED	82.30	82.30
1	BRACKET FRT BUMPER EXTENS	NOT NECESSARY	99.00	-
1	PRIG4 UNIT ASSY HEADLAMP	CUT	3,455.00	3,455.00
1	PRIG4 LAMP ASSY FOG RH	CUT	920.00	920.00
1	PRIG4 FENDER SUB-ASSY FRO	BENT	945.30	945.30
1	PRIG4 EMBLEM SIDE PANEL	NECESSARY	86.50	86.50
1	PRIG4 LINER FRONT FENDER	MISSING	198.50	198.50
2	PRIG4 RETAINER FRONT FEND	NOT NECESSARY	76.00	-
2	PRIG4 CLIP PIN HOLD	NOT NECESSARY	12.40	-
1	PRIG4 COVER FRONT BUMPER	NOT NECESSARY	28.38	-
1	PRIG4 JAR ASSY-WINDSHIEL	DEFORMED	183.75	183.75
	LESS 25% DISCOUNT		-1,652.26	-1,598.31
			4,956.77	4,794.94
	<u>LABOUR</u>			
	TOWING FEE.		60.00	-
	PANEL BEATING.		700.00	480.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
			1,310.00	940.00
	GRAND TOTAL		6,266.77	5,734.94





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,600.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC20014249/T1tf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser