



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8656E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER COVER	DEFORMED	1,052.20	1,052.20
1	I40VC PANEL-FENDER RH	BENT	663.00	663.00
1	I40VC LAMP ASSY-HEAD RH	NOT NECESSARY	1,800.00	-
1	BRACKET-FR BUMPER SIDE RH	NOT NECESSARY	24.60	-
1	BRKT ASSY-FR BPR UPR SIDE	NOT NECESSARY	22.40	-
1	I40VC CAP ASSY-WHEEL HUB	CUT	217.20	217.20
	LESS 20% DISCOUNT		-755.88	-386.48
			3,023.52	1,545.92
	<u>SPECIAL NETT ITEMS</u>			
1	FRT RH TYRE (60%)(SN)	CUT	216.00	129.60
			216.00	129.60
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	420.00
	SPRAYPAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
			1,200.00	880.00
GRAND TOTAL			4,439.52	2,555.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,050.00

Report Ref No. NS/INC20014252/T1qf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.