

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20014255/KTD3E2

Date: 09/04/2021

REFERENCE

Insured/Claimant: MOHAMMED NIZZAAR BIN ABDUL NAZZEER Policy No: DMPCSNW00116882000
Date of Loss: 17/12/2020 Nature of Claim: OD Claim No: SNM20D204954/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH5233Z**
Make & Model: HONDA CIVIC, 2.0 R (M) Engine No: K20Z23501586
Reg. Date: 16/06/2008 (Man. Year: 2008) Chassis No: JHMFD25408S201586
Colour: White Odometer: 0 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$22,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
Front Left Side: TOUR ROAD 9 mm Rear Left Side: TOUR ROAD 9 mm
Front Right Side: TOUR ROAD 9 mm Rear Right Side: TOUR ROAD 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,233.00	25.00	4,208.00	99.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	722.40	722.40	0.00	0.00
Paintwork Labour	126.69	126.69	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,082.09	874.09	4,208.00	82.80
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	5,082.09	624.09	4,458.00	87.72
+ GST 7.00/7.00% (S\$)	355.75	43.69	312.06	87.72
Nett Amount (S\$)	5,437.84	667.78	4,770.06	87.72

INSPECTION

Date of Assignment: 22/12/2020 Present Location: Ding Auto Pte Ltd (HQ)
Date Inspected: 22/12/2020 Inspected At: Ding Auto Pte Ltd (HQ)
Blk 10, #01-20, Sin Ming Industrial Estate Sector C
Singapore 575645
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,503.00 NETT)

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	71.40	71.40
2	Total Paint Materials	New	55.29	55.29
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	722.40	722.40
			Gross Labour Cost (\$\$)	849.09
				849.09

Report was unsubmitted during this print-out.

< END OF ESTIMATES >