

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III20014261/KBA3Q2

**Date:** 15/03/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHD15S	<b>Insured Vehicle No :</b>	SHA4414M
Date of Loss: 17/12/2020	Nature of Claim: TP	Claim No: MCT20120338

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD15S</b>		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002527
Reg. Date:	02/10/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC281655
Colour:	Metallic White/Red	Odometer:	608775 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,504.98	2,630.41	2,874.57	52.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	1,365.00	3,385.00	71.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,254.98</b>	<b>3,995.41</b>	<b>6,259.57</b>	<b>61.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>(S\$)</b>	10,254.98	3,200.00	7,054.98	68.80
<b>+ GST 7.00/7.00% (S\$)</b>	717.85	224.00	493.85	68.80
<b>Nett Amount (S\$)</b>	<b>10,972.83</b>	<b>3,424.00</b>	<b>7,548.83</b>	<b>68.80</b>
<b>+ Loss of Use (5.0 x S\$40.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (5.0 x S\$81.13/day) (S\$)</b>		405.65		
<b>Nett Liability (S\$)</b>		<b>4,029.65</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,900.00</b>		

### INSPECTION

Date of Assignment:	18/12/2020	
Date Inspected:	18/12/2020	Inspected At: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD15S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled / Dented	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL
3	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
4	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
5	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
6	1		*FENDER PANEL REAR RH	Bent	1,933.20 FL	*1,933.20 FL
7	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
8	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
9	1		*TAILLAMP RH	Serviceable	401.40 FL	*- FL
10	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*65.00 FS
11	1		*SET FENDER SCREW	Not Necessary	60.00 FS	*- FS
12	1		*SET CLIP ,FRONT FENDER LINER	Not Necessary	65.00 FS	*- FS
13	1		*TYRE	Serviceable	300.00 FS	*- FS
14	1		*RIM	Serviceable	350.00 FS	*- FS
15	1		*RIM HUB CAP	Dented	250.00 FS	*250.00 FS
16	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
17	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
18	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,942.20</b>	<b>2,879.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	437.22	249.49
<b>Total Parts (\$)</b>	<b>5,504.98</b>	<b>2,630.41</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING FEES	New	170.00	0.00
2	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	300.00	0.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
4	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	120.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	100.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	600.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,750.00</b>	<b>1,365.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >