



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 9675H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL LAMP LH	BROKEN	209.80	209.80
1	REAR BUMPER	BROKEN	600.50	600.50
3	REAR BUMPER SIDE CLIP LH @\$15.00	BROKEN (2 PCS ONLY)	45.00	30.00
1	REAR FENDER LH	DENTED	2,010.20	2,010.20
1	REAR FENDER MUDGUARD LH	NOT NECESSARY	131.67	-
	LESS 10% DISCOUNT		-299.72	-285.05
			2,697.45	2,565.45
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT (SN)	NECESSARY	80.00	30.00
1	TAIL LAMP PROTECTOR LH (SN)	CUT	50.00	40.00
			130.00	70.00
<u>LABOUR</u>				
	TO CUT/WELD REAR FENDER,PANEL BEAT & INNER PANEL,REMOVE & REPLACE DAMAGED PARTS.		800.00	800.00
	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS.		150.00	30.00
	TO CHECK AND RECTIFY LIGHTING & WIRING.		50.00	30.00
	TO SPRAY PAINTING FOR REAR LH PORTIONS & AFFECTED AREAS.		800.00	400.00
			1,800.00	1,260.00
GRAND TOTAL			4,627.45	3,895.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/SMO20014265/EUqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.