

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQI20014266/GTF3Q2**Date:** 01/02/2021**REFERENCE**

Insured/Claimant: FANNIYAH ANIS Policy No: DMPPHQ19-007664
Date of Loss: 04/11/2020 Nature of Claim: OD Claim No: DM20HO01637

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP1812D**
Make & Model: VOLKSWAGEN BEETLE, 1.2 (A) Engine No: CYV586944
Reg. Date: 30/11/2018 (Man. Year: 2017) Chassis No: WVVZZZ16ZJM709940
Colour: Grey Odometer: 23576 km
Engine Capacity: 1197 cc
Market Value/New Car Price: S\$88,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45Z R18 Rear Tyre Size: 235/45Z R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,269.80	3,609.00	3,660.80	50.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	970.00	2,130.00	68.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,369.80	4,579.00	5,790.80	55.84
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	10,369.80	4,329.00	6,040.80	58.25
+ GST 7.00/7.00% (S\$)	725.89	303.03	422.86	58.25
Nett Amount (S\$)	11,095.69	4,632.03	6,463.66	58.25

INSPECTION

Date of Assignment: 22/12/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Ubi)
Date Inspected: 30/12/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Ubi)
320 UBI ROAD 3
Singapore 408649
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	143	VOLKSWAGEN BEETLE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP1812D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*LHF HEAD LAMP	Cracked	1,450.00 F	*1,450.00 F
2	1	*LHF HEAD LAMP BRACKET LOWER	Not Necessary	120.00 F	*- F
3	1	*LHF FENDER	Buckled	300.00 F	*300.00 F
4	1	*LHF FENDER COWLING	Deformed	85.00 F	*85.00 F
5	1	*FRONT BUMPER	Deformed	680.00 F	*680.00 F
6	1	*FRONT BUMPER SIDE RETAINER LH	Cut	30.00 F	*30.00 F
7	1	*FRONT BUMPER SIGNAL LH	Not Necessary	68.00 F	*- F
8	1	*FRONT BUMPER SIGNAL COVER WITH CHROME LH	Cut	150.00 F	*150.00 F
9	1	*FOG LAMP LH	Not Necessary	110.00 F	*- F
10	1	*FOG LAMP LH COVER WITH CHROME	Not Necessary	150.00 F	*- F
11	1	*ABS PUMP ASSY	Not Necessary	2,500.00 F	*- F
12	1	*BRAKE MASTER PUMP	Not Necessary	380.00 F	*- F
Supplementary #1					
13	1	*LHF FENDER BRACKET	Broken	35.00 F	*35.00 F
14	1	*FRONT BUMPER SPONGE LH	Cracked	90.00 F	*90.00 F
15	1	*FRONT REINFORCEMENT	Bent	300.00 F	*300.00 F
16	1	*LH HEADLAMP BASE	Broken	120.00 F	*120.00 F
17	1	*FRONT NUMBER PLATE WITH CASING	Cracked	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	6,613.00	3,285.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	656.80	324.00
Total Parts (\$\$)	7,269.80	3,609.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKET AND ETC	New	100.00	50.00
2	TO REMOVE BRAKE MASTER , ABS PUMP ASSY .	New	380.00	0.00
3	REPROGRAMMING ABS SYSTEM	New	480.00	0.00
4	WHEEL ALIGNMENT	New	120.00	0.00
5	TO KNOCK & REPAIR FRONT BONNET , LHF FENDER INNER PANEL AND AFFECTED AREA .	New	900.00	480.00
6	TO PUTTY AND SPRAY PAINT FRONT BONNET , LHF FENDER , INNER PANEL , BUMPER AND AFFECTED AREA .	New	1,120.00	440.00
Gross Labour Cost (\$)			3,100.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >