

bul.

EQ

+

ASSIGNMENT

Estimated Cost
Y/TP/WS/TP RES/OD RES/EVA/INV/MV

Inspect Vehicle No:

Workshop m/s

Insured:
Policy No.

Claims No.

Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value:

JAC Accident Report:

RIA / PR Seen:

Est. Repairs:

Sum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

Type: M/Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp Reading

Eng/No

C/No

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Regn:

30 Nov 2018

1.2

CC 1197

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Volks wagen

Beetle

Grey

23576

www888168 JM 709940

Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Nil / S/Rim / STD A/Rim or

F:

R:

235/45ZR18

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

6

6

04/11/2020

W/S

6

6

30-12-20

11:30

24 N/S

Date / Time

Action / Instruction

30/12

Tyre is ok. Brake in order.

~~Suggest to get VW brake report for further investigation~~

Tyre is in serviceable condition. Brakes tested and found in ~~without~~ without any abnormality.

26/1

Finalized \$4579 with Tinie (red: 5790.80 : 5590)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Date/Time, File Pass to?

Date/Time, File Return to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp: (\$

Interview: (\$

Final Insp: (\$

Resurvey: (\$

Survey Fee:

Transportation:

1st Trip: (\$

2nd Trip: (\$

3rd Trip: (\$

4th Trip: (\$

5th Trip: (\$

6th Trip: (\$

7th Trip: (\$

8th Trip: (\$

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

320 UBI ROAD 3
Singapore 408649
Email: denisteo@cdge.com.sg

INSURER: **EQ Insurance Company Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPPHQ19-007664	Date of Loss:	04/11/2020
Vehicle Reg. No.:	SMP1812D	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FANNIYAH ANIS		
Make/Model:	VOLKSWAGEN BEETLE, 1.2 (A)	Vehicle Reg. Date:	30/11/2018
Vehicle Colour:	GREY		
Engine No:	CYV586944	Chassis No:	WVWZZZ16ZJN709940
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (UBI)		

COST OF CLAIMS

	Amount
Parts	6,625.30
Miscellaneous Items	0.00
Labour	3,100.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,725.30
+ GST 7.00% (\$\$)	680.77
Nett Amount (\$\$)	10,406.07

This claim is handled by: **TINIE**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Guo Qiang @ lkk auto.com

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Excess \$ 250
Not Authorised
30/12/2020
Guo Qiang - 82880282
(LKK)
40 days.
part by part.
before paint photos.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2020 13:34
Date Of Accident	04/11/2020 08:30
Exact Location Of Accident	CAR PARK SKH (STAFF CAR PARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP1812D
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	FANNIYAH ANIS
NRIC No	SXXXX708G
Email Address	FANNIYAH.ANIS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-86133766
Alternative Phone No	OTHERS-86133766

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	BEETLE 1.2 TSI

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	REPORTING ONLY
--	----------------

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ19-007664
Cover Note Number	28/11/2019 - 27/11/2020

Driver

Name of Driver	FANNIYAH ANIS
NRIC No	SXXXX708G
Date Of Birth	24/08/1988
Occupation	INDOOR
Date Of Driving Pass	15/01/2015
Driving Experience	5 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-86133766
Fax Number	
Contact Number	OTHERS-86133766
Email Address	FANNIYAH.ANIS@GMAIL.COM

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 14 Dec 2020)**Parts:** 143 VOLKSWAGEN BEETLE 1.2 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SMP1812D/14/12/2020 16:13**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHF HEAD LAMP / CAA	0.00	0.00	*1,450.00 F ✓
2	1		*LHF HEAD LAMP BRACKET LOWER 8 NN	0.00	0.00	*120.00 F ✓
3	1		*LHF FENDER / Bmc	0.00	0.00	*300.00 F ✓
4	1		*LHF FENDER COWLING / RE	0.00	0.00	*85.00 F ✓
5	1		*FRONT BUMPER / RE	0.00	0.00	*680.00 F ✓
6	1		*FRONT BUMPER SIDE RETAINER LH / Cut	0.00	0.00	*30.00 F ✓
7	1		*FRONT BUMPER SIGNAL LH X NN	0.00	0.00	*68.00 F ✓
8	1		*FRONT BUMPER SIGNAL COVER WITH CHROME LH / Cut	0.00	0.00	*150.00 F ✓
9	1		*FOG LAMP LH X	0.00	0.00	*110.00 F ✓
10	1		*FOG LAMP LH COVER WITH CHROME X	0.00	0.00	*150.00 F ✓
11	1		*ABS PUMP ASSY X	0.00	0.00	*2,500.00 F ✓
12	1		*BRAKE MASTER PUMP X	0.00	0.00	*380.00 F ✓

F=Franchise part.

Sub Total (\$)	6,023.00
+ Margin on L,N Items 10.00% (\$)	602.30
Total Parts (\$)	6,625.30

ComfortDelGro Engineering Pte Ltd/SMP1812D/14/12/2020 16:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Repairer Estimates

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKET AND ETC	New	50	100.00
2	TO REMOVE BRAKE MASTER , ABS PUMP ASSY .	New	8	380.00
3	REPROGRAMMING ABS SYSTEM	New	240	480.00
4	WHEEL ALIGNMENT	New	2	120.00
5	TO KNOCK & REPAIR FRONT BONNET , LHF FENDER INNER PANEL AND AFFECTED AREA .	New	480	900.00
6	TO PUTTY AND SPRAY PAINT FRONT BONNET , LHF FENDER , INNER PANEL , BUMPER AND AFFECTED AREA .	New	440	1,120.00

Gross Labour Cost (\$\$) 970 3,100.00

ComfortDelGro Engineering Pte Ltd/SMP1812D/14/12/2020 16:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4579

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display managing list during resurvey
- Parts price to be confirmed
- Third party survey on "Without Prejudice" basis
- No file to be created
- Supply of parts to be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 20 Jan 2021)

Parts: 143 **VOLKSWAGEN BEETLE 1.2 (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **ComfortDelGro Engineering Pte Ltd/SMP1812D/20/01/2021 16:31**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHF FENDER BRACKET / BR	0.00	0.00	*35.00 F
2	1		*FRONT BUMPER SPONGE LH / QA	0.00	0.00	*90.00 F
3	1		*FRONT REINFORCEMENT / BT	0.00	0.00	*300.00 F
4	1		*LH HEADLAMP BASE / BR	0.00	0.00	*120.00 F
5	1		*FRONT NUMBER PLATE WITH CASING / QA	0	0.00	*45.00 FS
Sub Total (\$\$)						590.00
+ Margin on L,N Items 10.00% (\$\$)						54.50
Total Parts (\$\$)						644.50

F=Franchise part. S=SpcNett.

ComfortDelGro Engineering Pte Ltd/SMP1812D/20/01/2021 16:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

ence

Source: MRM-SG

Version: 1.0 (Last Synchronised: 14 Dec 2020)

143

VOLKSWAGEN BEETLE 1.2 (A) (Catalogue: Merimen Singapore 1.0)

Repaire's

(Price-denominated Standard List)

Code: ComfortDelGro Engineering Pte Ltd/SMP1812D/14/12/2020 16:13

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Other Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No. Particulars

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHF HEAD LAMP / CAA			
2	1		*LHF HEAD LAMP BRACKET LOWER X			
3	1		*LHF FENDER / Bnc	0.00	0.00	*1,450.00 F
4	1		*LHF FENDER COWLING / RR	0.00	0.00	*120.00 F
5	1		*FRONT BUMPER / RR	0.00	0.00	*300.00 F
6	1		*FRONT BUMPER SIDE RETAINER LH / Cut	0.00	0.00	*85.00 F
7	1		*FRONT BUMPER SIGNAL LH X	0.00	0.00	*680.00 F
8	1		*FRONT BUMPER SIGNAL COVER WITH CHROME LH / Cut	0.00	0.00	*30.00 F
9	1		*FOG LAMP LH X	0.00	0.00	*68.00 F
10	1		*FOG LAMP LH COVER WITH CHROME X X	0.00	0.00	*150.00 F
11	1		*ABS PUMP ASSY X	0.00	0.00	*110.00 F
12	1		*BRAKE MASTER PUMP X	0.00	0.00	*150.00 F
				0.00	0.00	*2,500.00 F
				0.00	0.00	*380.00 F

=Franchise part.

Sub Total (S\$)

+ Margin on L,N Items 10.00% (S\$)

6,023.00

602.30

Total Parts (S\$)

6,625.30

ComfortDelGro Engineering Pte Ltd/SMP1812D/14/12/2020 16:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

⑤ Supplementary:

① Reinforcement - 1745390562 / BT

② Bumper sponge LH - 5C5 807 248 / CAA /

③ LHF fender bracket - 505 807773 / BR /

④ Bumper lower grille - 5C5 853 677 / BR

⑤ Bumper lower grille chrome moulding - / Sir.

Quo Quay

13/1/2021

processed to order.