

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2103084

3 ANSON ROAD #16-00 INV Date 03/05/2021

SPRINGLEAF TOWER
SINGAPORE 079909
Reference CC3/CTI20014267/Kra3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5188T

Insured Veh. GBJ 7357Z

Claim No. SNM20D204975/LKKDS

Policy No. DMCVSNW00055242001

Accident Date 16/12/2020

Inspection Date 21/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CC3/CTI20014267/Kra3q2	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	03/05/2021	
				Code:	CTI	
1.		Policy Particulars	:- THIRD PARTY	CLAIN	1	
	Insured Veh.	GBJ 7357Z	Veh. Inspected		SHD 5188T	
	Policy No.	DMCVSNW00055242001	Coverage (\$)		0.00	
	Claim No.	SNM20D204975/LKKDS	Excess (\$)		0.00	
	Assign From		Assign Date		21/12/2020	
2.		Vehicle Partic	culars & Conditi	on		
	Make & Model TOYOTA PRIUS (A) c.c 1798				1798	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JTDKB3FU903077057	Colour		M . P. WHITE / RED	
	Odometer	244056 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	SAILUN		9 mm	
	L/H Front Tyre	195/65 R15	SAILUN		9 mm	
	R/H Rear Tyre	195/65 R15	SAILUN		9 mm	
	L/H Rear Tyre	195/65 R15	SAILUN		9 mm	
4.	Description of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR O/S PORTION	•		
	DAMAGES SEE DETAILS.					
5.		General	Information			
	Accident Date	16/12/2020	Inspection Dat	е	21/12/2020	
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate	Days of Repair			
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		2 Work	ing Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5188T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER ,REAR BUMPER	BUCKLED	442.60	442.60
1	REINFORCEMENT SUB-ASSY ,REAR BUMPER	TO REPAIR SEE LABOUR	332.70	-
1	GUARD ,REAR BUMPER ,CENTER	DENTED / CUT	576.30	576.30
1	COVER ,REAR BUMPER ,LOWER	SERVICEABLE	15.40	-
1	RETAINER ,REAR BUMPER SIDE ,LH	SERVICEABLE	116.50	-
1	RETAINER ,REAR BUMPER SIDE ,RH	SERVICEABLE	117.70	-
1	FILLER ,REAR BUMPER EXTENSION ,RH	SERVICEABLE	123.70	-
1	SEAL ,REAR BUMPER SIDE ,LH	SERVICEABLE	88.50	-
1	SEAL ,REAR BUMPER SIDE ,RH	DISTORTED	88.50	88.50
1	LENS & BODY ,REAR COMBINATION LAMP ,RH	CRACKED	451.80	451.80
1	LENS AND BODY ,REAR LAMP ,RH	CUT	502.00	502.00
1	PANEL SUB-ASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	650.30	-
1	COVER ,FLOOR UNDER ,NO.1 (LH)	SERVICEABLE	175.10	-
1	COVER ,FLOOR UNDER ,NO.2 (RH)	SERVICEABLE	241.90	-
1	COVER ,REAR FLOOR (CTR)	SERVICEABLE	229.90	-
	LESS 25% DISCOUNT		-1,038.23	-515.30
			3,114.67	1,545.90
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	95.00	60.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	180.00	30.00
1	SET REAR FENDER LINER CLIP (SN)	NOT NECESSARY	85.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
1	REAR BUMPER PLATE WITH HOLDER (SN)	SERVICEABLE	140.00	-
1	SET TAILLAMP LOWER CLIP (SN)	NECESSARY	55.00	10.00
1	SET TAILLAMP UPPER CLIP (SN)	NECESSARY	55.00	10.00
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	65.00	-
			1,460.00	110.00

Report Ref No. CC3/CTI20014267/Kra3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY ,REAR BUMPER AND PANEL SUB-ASSY ,BODY LOWER BACK .		2,200.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR .	NOT NECESSARY	480.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	480.00	-
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-IN-GAS.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR .	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .	NOT NECESSARY	220.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	TOWING FEES.	NOT NECESSARY	150.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		2,200.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED .		170.00	20.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING .	NOT NECESSARY	220.00	-
	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR .	NOT NECESSARY	170.00	-
	TO LIFT-UP /OUT ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS - MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR .	NOT NECESSARY	380.00	-

Report Ref No. CC3/CTI20014267/Kra3q2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

2,145.90

TO CONDUCT AND PERFORM A COMPREHENSIVE NOT NECESSARY 380.0 VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE	NOT NECESSARY	380.00	-
9,990.0			9,990.00	490.00
GRAND TOTAL 14,564.6	GRAND TOTAL		14,564.67	2,145.90

Report Ref No. CC3/CTI20014267/Kra3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5188T

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5188T

RE-INSPECTION



