

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20014270/QEA3Q2
Date: 29/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100471730
Claimant Vehicle No :	SG5870K	Insured Vehicle No :	SLC7709K
Date of Loss:	10/12/2020	Nature of Claim:	TP
		Claim No:	9730787703SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5870K	Engine No:	50344832274486
Make & Model:	MAN A95, 10.5 D (A)	Chassis No:	WMAA95ZZ8G7003550
Reg. Date:	16/11/2017 (Man. Year: 2016)	Odometer:	208706 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	480.00	432.00	48.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,227.00	792.00	435.00	35.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,707.00	1,224.00	483.00	28.30
Approved Total (Overridden) (S\$)		1,150.00		

Nett Amount (S\$)	1,707.00	1,150.00	557.00	32.63
+ Loss of Use (2.0 x S\$325.00/day) (S\$)		650.00		
(S\$)		1,800.00		
Liabe Amount (50.00%) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		907.00		

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020

Estimated Period of Repair: 1.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE LAMP BULB (A95 MAN)	Cracked	235.00 F	*235.00 FL
2	1		*REAR LAMP BULB (A95 MAN)	Cracked	245.00 F	*245.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)						480.00
- List Item Discount on L Items 0.00/10.00% (\$)						0.00
Total Parts (\$)						480.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	TO PUTTY & RESPRAY	New	432.00	262.00
Gross Labour Cost (S\$)			1,227.00	792.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >