LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

ΤP

CS3/AIG20014272/QQD3E2

Date:

04/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2070064983

Claimant Vehicle No

SLT8707U

Insured Vehicle No:

GBA2886T

Date of Loss:

16/12/2020

Nature of Claim:

Claim No:

6969243066SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLT8707U

Make & Model:

HONDA HR-V, 1.5 (A)

Reg. Date: 15/11/2017 (Man. Year: 2017)

Engine No: Chassis No: Odometer

JHMRU1810GX203182

L15B4533182

103305 km

Colour: Engine Capacity: Black

Market Value/New Car Price:

1496 сс

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Dunlop 6 mm

Rear Left Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

Front Right Side: Dunlop 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

21/12/2020

Ann Joo Motor Pte Ltd (HQ)

Date Inspected:

23/12/2020

Inspected At: Blk 176 Sin Ming Drive #02-17, Singapore 575721

Estimated Period of Repair: 2.0 days

Singapore 575721

Adjuster: OI SUN PIN Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*-F
2	1		*FRT GRILLE	Cracked	0.00 F	*- F
3	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
4	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
F=Fra	anchise	part.		Total Parts (S\$)	0.00	0.00
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >