

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION RE	PORT		
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO20014274/GUtd3e2	
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND PRE 048623		Date:	08/01/2021	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLS 2126R	Veh. Inspected	d	SKG 6713U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2003744/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		22/12/2020	
2.	Vehicle Particulars & Condition					
	Make & Model	B.M.W. 116I	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	WBA1A12030E948896	Colour		GREY	
	Odometer	149451 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40Z R18	PIRELLI		6 mm	
	L/H Front Tyre	225/40Z R18	PIRELLI		6 mm	
	R/H Rear Tyre	225/40Z R18	PIRELLI		6 mm	
	L/H Rear Tyre	225/40Z R18	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
5.	5. General Information					
	Accident Date	19/12/2020	Inspect Date /	Time	22/12/2020 (04:30 PM)	
	Survey held at	CARSMITH PTE LTD	•			
	BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
1	Estimate Days of Repair					
5b.		Estimate	Days of Repair	ſ		

Report Ref No. CS3/SMO20014274/GUtd3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE