

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014277/KQD3Q2

Date: 22/02/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No: 0999993862

Date of Loss: 03/12/2020

Nature of Claim:

OD

Claim No:

0706892309SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ5855A**

Make & Model: BMW 320I, 2.0 (A)

Engine No: F8563622B48B20A

Reg. Date: 22/09/2020 (Man. Year: 2020)

Chassis No: WBA5F320X0FJ50386

Colour: Metallic Grey

Odometer: 7914 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$172,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R18

Rear Tyre Size:

225/45R18

Front Left Side: Hankook 9 mm

Rear Left Side:

Hankook 9 mm

Front Right Side: Hankook 9 mm

Rear Right Side:

Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,678.85	7,521.60	3,157.25	29.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,920.00	1,580.00	45.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,178.85	9,441.60	4,737.25	33.41
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	12,978.85	8,241.60	4,737.25	36.50
+ GST 7.00/7.00% (S\$)	908.52	576.91	331.61	36.50
Nett Amount (S\$)	13,887.37	8,818.51	5,068.86	36.50

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 22/12/2020 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-RH (WCP)	Bent	1,680.00 F	*1,680.00 F
2	1		*REAR DOOR WEATHERSTRIP-RH (WCP)	Necessary	225.00 F	*225.00 F
3	20		*REAR DOOR TRIMBOARD RIVETS-RH (WCP)	Necessary	231.00 FS	*60.00 FS
4	1		*REAR DOOR OUTER HANDLE-RH (WCP)	Broken	188.00 F	*188.00 F
5	1		*REAR DOOR OUTER HANDLE GRIP-RH (WCP)	Missing	25.00 F	*25.00 F
6	1		*REAR FENDER-RH (WCP)	Bent	2,100.00 F	*2,100.00 F
7	1		*REAR FENDER INNER PANEL-RH (WCP)	Repair	1,625.00 F	*- F
8	1		*REAR FENDER INNER SHIELD-RH (WCP)	Cracked	230.00 F	*230.00 F
9	20		*REAR FENDER INNER SHIELD CLIPS-RH (WCP)	Necessary	143.00 FS	*50.00 FS
10	1		*REAR PETROL FLAP (WCP)	Missing	85.00 F	*85.00 F
11	1		*REAR PETROL HOUSING (WCP)	Cracked	158.00 F	*158.00 F
12	1		*REAR BUMPER (WCP)	Bent/Cracked	1,550.00 F	*1,550.00 F
13	1		*REAR BUMPER SIDE RETAINER-RH (WCP)	Cracked	265.00 F	*265.00 F
14	1		*REAR BUMPER SENSOR (WCP)	Serviceable	255.00 F	*- F
15	6		*REAR BUMPER SENSOR SEALS (WCP)	Necessary	72.00 F	*72.00 F
16	1		*REAR BUMPER CLIPS (WCP) (15 PCS)	Necessary	90.75 FS	*50.00 FS
17	1		*TAILLAMP ASSY-RH (WCP)	Serviceable	695.00 F	*- F
18	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
19	1		*REAR FENDER INNER FUSE BOX COVER (WCP)	Cracked	78.00 F	*78.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	9,755.75	6,856.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	923.10	665.60
Total Parts (\$\$)	10,678.85	7,521.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
2	TO REMOVE AND REFIT REAR PETROL TANK	New	220.00	60.00
3	TO REMOVE AND REFIT RH REAR INTERIOR GARNISHES, TRIMBOARDS AND SPEAKER BOARD TO FACILITATES THE REPAIRS	New	280.00	120.00
4	TO TRANSFER RH REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	150.00	60.00
5	TO PANEL BEAT AND STRAIGHTEN RH REAR CHASSIS FRAME, RH REAR DOOR PILLAR, TO CUT AND WELD RH REAR FENDER, RH REAR FENDER INNER PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,500.00	900.00
6	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	660.00
Gross Labour Cost (\$\$)			3,500.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >