

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014279/AQD3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00122542000

Claimant Vehicle No : SLK1857M Insured Vehicle No : SBC4444L

Date of Loss: 18/12/2020 Nature of Claim: TP Claim No: SNM20D204944/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK1857M**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZRY347113

Reg. Date: 09/01/2017 (Man. Year: 2016) Chassis No: MR053REH104562510

Colour: Blue Odometer: 33375 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,671.89	4,279.48	4,392.41	50.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,900.00	800.00	21.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,371.89	7,179.48	5,192.41	41.97
Approved Total (Overridden) (S\$)		5,750.00		
Nett Amount (S\$)	12,371.89	5,750.00	6,621.89	53.52

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 22/12/2020 Inspected At: Chin Meng Motors (HQ)
1 Kaki Bukit Ave 6 #01-40/63, Autobay
@ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK1857M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	781.40 FL	*781.40 FL
2	1		*BOOTLID EMBLEM-LOGO	Necessary	61.10 FL	*61.10 FL
3	1		*BOOTLID EMBLEM-COROLLA	Necessary	63.90 FL	*63.90 FL
4	1		*BOOTLID EMBLEM-ALTIS	Necessary	51.90 FL	*51.90 FL
5	1		*BOOTLID LAMP	N/s Cut	743.50 FL	*328.00 FL
6	2		*BOOTLID HINGES	Not Necessary	364.10 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Cut	231.35 FL	*231.35 FL
8	1		*BOOTLID INNER LOCK	Not Necessary	371.75 FL	*- FL
9	1		*BOOTLID INSULATOR	Not Necessary	261.60 FL	*- FL
10	11		*BOOTLID INSULATOR CLIPS	Not Necessary	38.50 FL	*- FL
11	4		*BOOTLID STOPPERS	Not Necessary	50.00 FL	*- FL
12	1		*TAILLAMP L/H	Cracked	412.50 FL	*391.00 FL
13	1		*TAILLAMP CLIP L/H	Necessary	10.00 FL	*10.00 FL
14	1		*TAILLAMP LOWER BRACKET	N/s Damaged	171.25 FL	*48.00 FL
15	1		*REAR BUMPER	Distorted	571.45 FL	*571.45 FL
16	1		*REAR BUMPER RETAINERS	N/s Damaged	181.74 FL	*90.87 FL
17	1		*REAR BUMPER BRACKETS	N/s Dented	362.20 FL	*165.00 FL
18	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	371.75 FL	*371.75 FL
20	1		*REAR WINDSCREEN MOULDING	Necessary	133.52 FL	*133.52 FL
21	1		*REAR L/H FENDER	Distorted	1,712.55 FL	*986.00 FL
22	1		*REAR L/H FENDER INNER TRIM BOARD	Crumpled	381.60 FL	*338.00 FL
23	6		*REAR L/H FENDER INNER TRIM BOARD CLIPS	Necessary	21.00 FL	*21.00 FL
24	1		*REAR L/H FENDER MUDFLAP	Not Necessary	98.50 FL	*- FL
25	1		*REAR L/H FENDER AIR DUCT	Cracked	78.50 FL	*78.50 FL
26	1		*REAR L/H FENDER INNER PANEL	Repair	678.90 FL	*- FL
27	1		*FUEL TANK	Not Necessary	971.75 FL	*- FL
28	1		*FUEL TANK NECK	Not Necessary	189.50 FL	*- FL
29	1		*REAR END PANEL	Dented	381.90 FL	*381.90 FL
30	1		*REAR END PANEL GARNISH	Deformed	371.44 FL	*240.00 FL
31	1		*REAR END PANEL GARNISH INNER COVER	Not Necessary	171.10 FL	*- FL
32	1		*SPARE TYRE PANEL	Repair	807.00 FL	*- FL
33	2		*REAR BUMPER SENSORS	Damaged	277.95 FS	*200.00 FS
34	1		*REAR WINDSCREEN GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,453.20	5,622.64
- List Item Discount on L Items 25.00/25.00% (\$)	2,781.31	1,343.16
Total Parts (\$)	8,671.89	4,279.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEATING,WELDING,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE PARTS AS MENTIONED ABOVE ETC	New	1,500.00	1,200.00
2	TO RESPRAY AFFECTED PART	New	1,600.00	1,200.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE & REFIT REAR INNER TRIMS,SEAT ASSY AND ROOF LINING TO FACILITATE REPAIR	New	150.00	80.00
5	TO REMOVE & REFIT FUEL TANK	New	100.00	80.00
6	TO REMOVE & REFIT REAR REVERSE SENSOR	New	60.00	50.00
7	TOWING CHARGES	New	60.00	60.00
8	TO APPLY UNDERSEAL	New	80.00	80.00
9	TO REMOVE & REFIT OF WIRINGS	New	30.00	30.00
Gross Labour Cost (\$\$)			3,700.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >