

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI20014281/T1QD3Q2

**Date:** 01/02/2021

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MS010952

**Claimant**

**Vehicle No :** SHD6655E

**Insured Vehicle No :** SFV2000A

Date of Loss: 19/12/2020

Nature of Claim: TP

Claim No: M2006290

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD6655E**

Make & Model: MERCEDES-BENZ E220, 2.1 D CDI  
BlueEFFICIENCY (A)

Engine No: 65192433220474

Reg. Date: 23/03/2016 (Man. Year: 2015)

Chassis No: WDD2120012B307939

Colour: White

Odometer: 751961 km

Engine Capacity: 2143 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

### CONDITION OF TYRES

Front Tyre Size:	225/55R16	Rear Tyre Size:	225/55R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,282.38	2,924.38	3,358.00	53.45
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,550.00	1,000.00	550.00	35.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,843.38</b>	<b>3,935.38</b>	<b>3,908.00</b>	<b>49.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	7,843.38	3,100.00	4,743.38	60.48
<b>+ GST 7.00/7.00% (S\$)</b>	549.04	217.00	332.04	60.48
<b>Nett Amount (S\$)</b>	<b>8,392.42</b>	<b>3,317.00</b>	<b>5,075.42</b>	<b>60.48</b>

### INSPECTION

Date of Assignment: 22/12/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 21/12/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
<b>Parts:</b>	143	MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD6655E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER ASSY FRONT	Deformed	1,890.50 FL	-	*1,890.50 FL
2	1		*BUMPER GRILLE FRT/LH	Not Necessary	240.50 FL	-	*- FL
3	1		*BUMPER BRACKET FRT/LH	Bent	95.00 FL	-	*95.00 FL
4	1		*BUMPER SIDE BEAM FRT/LH	Bent	26.90 FL	-	*26.90 FL
5	1		*FENDER FRT/LH	Bent	996.08 FL	-	*996.08 FL
6	1		*FENDER SPLASHSHEILD FRT/LH	Deformed	257.00 FL	-	*257.00 FL
7	1		*HEAD LAMP ASSY LH	Not Necessary	3,957.00 FL	-	*- FL
<b>Supplementary #1</b>							
8	1		*HEADLAMP PANEL LH	Bent	240.00 FL	-	*240.00 FL
9	1		*HEADLAMP BRACKET LH	Distorted	150.00 FL	-	*150.00 FL
					<b>Sub Total (S\$)</b>	<b>7,852.98</b>	<b>3,655.48</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,570.60</b>	<b>731.10</b>
					<b>Total Parts (S\$)</b>	<b>6,282.38</b>	<b>2,924.38</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	740.00	540.00
2	SPRAY PAINTING	New	600.00	400.00
3	CHECK LIGHTING	New	60.00	30.00
4	TUFF COATING	New	60.00	30.00
5	RESET WHEEL ALIGNMENT	New	90.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,550.00</b>	<b>1,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >