



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5485R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FENDER SUB-ASSY,FRONT RH	BENT	977.80	977.80
1	LINER,FRONT FENDER,RH	SERVICEABLE	206.70	-
1	PANEL SUB-ASSY,FRONT DOOR,RH	TO REPAIR SEE LABOUR	1,300.70	-
1	JAR ASSY,WINDSHIELD WASHER	SERVICEABLE	219.10	-
	LESS 25% DISCOUNT		-676.07	-244.44
			2,028.23	733.36
1	RIM	DENTED	1,879.40	1,555.10
1	HUB CAP	DENTED / CUT	300.00	175.80
	LESS 25% DISCOUNT		-	-432.73
			2,179.40	1,298.17
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT FENDER EMBLEM RH (SN)	NECESSARY	54.60	54.60
1	SET FRT FENDER CLIP (SN)	NOT NECESSARY	95.00	-
1	FRT FENDER LINER CLIP (SN)	NOT NECESSARY	180.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NECESSARY	85.00	60.00
1	TYRE (SN)	SERVICEABLE	350.00	-
			764.60	114.60
	<u>LABOUR</u>			
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY,FRONT DOOR,RH.		2,200.00	300.00
	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	480.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	30.00
	TOWING FEES.	NOT NECESSARY	150.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	440.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.		220.00	20.00
	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	-
			7,950.00	865.00
GRAND TOTAL			12,922.23	3,011.13
RECOMMENDED COST OF REPAIRS				3,011.13

Report Ref No. CS/SMO20014289/Kqd3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.