

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITA	AL INSURANCE LTD		Ref:	CS3/FCI20014298/Gqd3e2	
	36 ROBINSON RO HOUSESINGAPOR			Date:	04/01/2021	
				Code:	FCI2	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 4127S	Veh. Inspected	t	SKW 8661M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D20005231MFSH	Excess (\$)		0.00	
	Assign From	CHRIS LIM	Assign Date		22/12/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 316I 1.6	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WBA3A16070NS37575	Colour		WHITE	
	Odometer	105030 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R18	GOODYEAR		6 mm	
	L/H Front Tyre	225/45 R18	GOODYEAR		6 mm	
	R/H Rear Tyre	225/45 R18	GOODYEAR		6 mm	
	L/H Rear Tyre	225/45 R18	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE REAR O/S PORTION.				
5.	General Information					
	Accident Date	18/12/2020	Inspect Date /	Time	28/12/2020 (11:20 AM)	
	Survey held at	Survey held at TOP 93 PTE LTD				
	51 UBI AVENUE 1, #01-05, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$56,000.00					

Report Ref No. CS3/FCI20014298/Gqd3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor