

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III20014302/R1QD3E2

Date: 22/02/2022

REFERENCE

Insured/Claimant: TAN SIN HUI Policy No: D20MPC0002649
Date of Loss: 05/12/2020 Nature of Claim: OD Claim No: MPC2020D0002667

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR1975E**
Make & Model: HONDA JAZZ, 1.5 VTIR CVT (A) Engine No: L15B31191160
Reg. Date: 11/05/2017 (Man. Year: 2016) Chassis No: JHMGK5850HX201661
Colour: Grey Odometer: 0 km
Engine Capacity: 1498 cc
Market Value/New Car Price: S\$60,500.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,398.40	17,512.00	3,886.40	18.16
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,299.50	4,432.50	-2,133.00	-92.76
Paintwork Labour	1,156.63	2,138.98	-982.35	-84.93
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,865.53	24,094.48	771.05	3.10
Approved Total (Overridden) (S\$)		17,000.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	24,865.53	16,400.00	8,465.53	34.05
+ GST 7.00/7.00% (S\$)	1,740.59	1,148.00	592.59	34.05
Nett Amount (S\$)	26,606.12	17,548.00	9,058.12	34.05

INSPECTION

Date of Assignment: 24/12/2020

Date Inspected: 23/12/2020

Inspected At:

Mova Automotive Pte Ltd
15 Fan Yong Road
Singapore 629792

Estimated Period of Repair: 20.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2022)
Parts: 144	HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1975E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIRBAG	Activated	935.00 FL	*935.00 FL
2	1	NA	*AIRCON	Bent	710.00 FL	*710.00 FL
3	1	NA	*BADGE I-VTEC	Necessary	0.00 FL	*45.00 FL
4	1	NA	*BADGE JAZZ	Necessary	30.00 FL	*30.00 FL
5	1	NA	*BONNET	Bent	540.00 FL	*540.00 FL
6	1	NA	*BONNET LOCK	Bent	95.00 FL	*95.00 FL
7	1	NA	*BOOT/TAILGATE LOCK	Jammed	95.00 FL	*95.00 FL
8	1	NA	*BOOT/TAILGATE SEAL	Necessary	100.00 FL	*100.00 FL
9	1	NA	*BOOTFLOOR	Buckled	770.00 FL	*770.00 FL
10	1	NA	*BOOTLID/TAILGATE	Buckled	735.00 FL	*735.00 FL
11	1	NA	*CONTACT RING	Cracked	275.00 FL	*275.00 FL
12	1	NA	*DRIVER AIRBAG	Activated	1,640.00 FL	*1,640.00 FL
13	1	NA	*END PANEL TRIM	Deformed	75.00 FL	*75.00 FL
14	1	NA	*EXPANSION TANK	Cracked	30.00 FL	*30.00 FL
15	1	NA	*FRESH AIR GRILLE	Cracked	30.00 FL	*30.00 FL
16	1	NA	*FRONT BUMPER	Deformed	550.00 FL	*550.00 FL
17	1	NA	*FRONT PANEL CPL	Bent	395.00 FL	*395.00 FL
18	1	NA	*FRT BUMPER SUPPORT	Necessary	220.00 FL	*220.00 FL
19	1	NA	*FRT LH	Activated	550.00 FL	*550.00 FL
20	1	NA	*FRT LWR BUMP GRILLE	Cracked	45.00 FL	*45.00 FL
21	1	NA	*FRT NO PLATE REINF	Deformed	75.00 FL	*75.00 FL
22	1	NA	*FRT RH	Activated	550.00 FL	*550.00 FL
23	1	NA	*FRT X 2	Necessary	172.00 FL	*172.00 FL
24	1	NA	*GRILLE	Missing	300.00 FL	*300.00 FL
25	1	NA	*HIGH TONE HORN	Not Necessary	60.00 FL	*- FL
26	1	NA	*INSTRUMENT PANEL	Not Necessary	718.00 FL	*- FL
27	1	NA	*INTAKE MANIFOLD	Scratched	440.00 FL	*440.00 FL
28	1	NA	*L/BONNET HINGE	Bent	42.00 FL	*42.00 FL
29	1	NA	*L/FAN MOTOR	Necessary	290.00 FL	*290.00 FL
30	1	NA	*L/FAN SHROUD	Cracked	85.00 FL	*85.00 FL
31	1	NA	*L/F HEADLAMP	Cracked	1,176.00 FL	*1,176.00 FL
32	1	NA	*L/F OUT BUMPER BRKT	Necessary	20.00 FL	*20.00 FL
33	1	NA	*L/F UPP BUMPER BRKT	Necessary	65.00 FL	*65.00 FL
34	1	NA	*L/F WING	Repair	375.00 FL	*- FL
35	1	NA	*L/RADIATOR FAN	Cracked	75.00 FL	*75.00 FL
36	1	NA	*L/R BUMPER BRACKET	Necessary	30.00 FL	*30.00 FL
37	1	NA	*L/R BUMPER COVER	Not Necessary	30.00 FL	*- FL
38	1	NA	*L/R DRIP RAIL	Not Necessary	450.00 FL	*- FL
39	1	NA	*L/R LAMP	Cracked	105.00 FL	*105.00 FL
40	1	NA	*L/R LAMP	Cracked	307.00 FL	*307.00 FL
41	1	NA	*L/R SIDE PANEL TRIM	Deformed	303.00 FL	*303.00 FL
42	1	NA	*L/R WHEELHOUSE COVER	Not Necessary	40.00 FL	*- FL
43	1	NA	*L/R WINDOW SEAL	Necessary	56.00 FL	*56.00 FL
44	1	NA	*L/R WING	Bent	877.00 FL	*877.00 FL
45	1	NA	*L/TAILGATE DAMPER	Not Necessary	150.00 FL	*- FL
46	1	NA	*L/WHEELHOUSE SHELL	Not Necessary	172.00 FL	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1	NA	*LOWER TAILGATE TRIM	Not Necessary	200.00 FL	*- FL
48	1	NA	*LOW TONE HORN	Not Necessary	60.00 FL	*- FL
49	1	NA	*LUGG COMPART CARPET	Torn	298.00 FL	*298.00 FL
50	1	NA	*PASSENGER AIRBAG	Activated	2,236.00 FL	*2,236.00 FL
51	1	NA	*PLATFORM	Not Necessary	221.00 FL	*- FL
52	1	NA	*R/BONNET HINGE	Bent	42.00 FL	*42.00 FL
53	1	NA	*R/FAN MOTOR	Not Working	290.00 FL	*290.00 FL
54	1	NA	*R/FAN SHROUD	Cracked	85.00 FL	*85.00 FL
55	1	NA	*R/F HEADLAMP	Cracked	1,176.00 FL	*1,176.00 FL
56	1	NA	*R/F OUT BUMPER BRKT	Necessary	20.00 FL	*20.00 FL
57	1	NA	*R/F UPP BUMPER BRKT	Necessary	65.00 FL	*65.00 FL
58	1	NA	*R/F WING	Bent	375.00 FL	*375.00 FL
59	1	NA	*R/RADIATOR FAN	Cracked	75.00 FL	*75.00 FL
60	1	NA	*R/R BUMPER BRACKET	Necessary	30.00 FL	*30.00 FL
61	1	NA	*R/R BUMPER COVER	Not Necessary	30.00 FL	*- FL
62	1	NA	*R/R DRIP RAIL	Not Necessary	450.00 FL	*- FL
63	1	NA	*R/R LAMP	Cracked	105.00 FL	*105.00 FL
64	1	NA	*R/R LAMP	Broken	307.00 FL	*307.00 FL
65	1	NA	*R/R SIDE PANEL TRIM	Deformed	303.00 FL	*303.00 FL
66	1	NA	*R/R WHEELHOUSE CVR	Not Necessary	40.00 FL	*- FL
67	1	NA	*R/R WINDOW SEAL	Necessary	56.00 FL	*56.00 FL
68	1	NA	*R/R WING	Bent	877.00 FL	*877.00 FL
69	1	NA	*R/TAILGATE DAMPER	Not Necessary	150.00 FL	*- FL
70	1	NA	*R/WHEELHOUSE SHELL	Not Necessary	172.00 FL	*- FL
71	1	NA	*RAD GRILLE COVER	Deformed	130.00 FL	*130.00 FL
72	1	NA	*RADIATOR	Bent	1,187.00 FL	*1,187.00 FL
73	1	NA	*REAR BUMPER	Deformed	495.00 FL	*495.00 FL
74	1	NA	*REAR CARRIER	Not Necessary	150.00 FL	*- FL
75	1	NA	*REAR PANEL	Bent	430.00 FL	*430.00 FL
76	1	NA	*REAR SCREEN BOND KIT (NPA)	Not Necessary	0.00 FL	*- FL
77	1	NA	*REAR SCREEN CLAMPS (NPA)	Not Necessary	0.00 FL	*- FL
78	1	NA	*REAR SCREEN CLAMPS (NPA)	Not Necessary	0.00 FL	*- FL
79	1	NA	*REAR SCREEN CLAMPS (NPA)	Not Necessary	0.00 FL	*- FL
80	1	NA	*REAR SCREEN FIX SET (NPA)	Not Necessary	0.00 FL	*- FL
81	1	NA	*REAR WIPER MOTOR	Not Necessary	200.00 FL	*- FL
82	1	NA	*RIGHT ENGINE SUPPORT	Not Necessary	220.00 FL	*- FL
83	1	NA	*STARTER MOTOR	Not Necessary	630.00 FL	*- FL
84	1	NA	*TAILGATE HANDLE MLDG	Not Necessary	212.00 FL	*- FL
85	1	NA	*UP/CVR RADIAT GRILLE	Deformed	25.00 FL	*25.00 FL
86	1	NA	*SUNDRY PARTS	Not Necessary	2.00 FL	*- FL
87	1	NA	*AUDATEX FEE		40.00 FL	*40.00 FS
88	1	NA	*FRT & REAR NO PLATE	Front Bent	100.00 FL	*50.00 FS
89	1	NA	*MERIMEN FEE		11.00 FL	*- FS
90	1	NA	*RAD COOLANT	Necessary	30.00 FL	*30.00 FS
91	1	NA	*REAR CAMERA	Not Necessary	200.00 FL	*- FS
92	1	NA	*REAR GLASS SEALANT	Necessary	40.00 FL	*40.00 FS
93	1	NA	*REAR PARKING SENSOR	Not Working	200.00 FL	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	26,748.00	21,800.00
- List Item Discount on L Items 20.00/20.00% (\$)	5,349.60	4,288.00
Total Parts (\$)	21,398.40	17,512.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	886.50	1,480.50
2	Total Paint Materials	New	270.13	658.48
Labour Items				
3	Total Panel/Mechanical Labour	New	2,286.00	4,419.00
4	Additional Total	New	13.50	13.50
			Gross Labour Cost (\$\$)	3,456.13
				6,571.48

Report was unsubmitted during this print-out.

< END OF ESTIMATES >