

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 24 Dec 2020

Preliminary Advice

Vehicle No	: SKR1975E	Accident Date	: 05/12/2020
Make	: HONDA JAZZ	Policy No.	: D20MPC0002649
Assignment Date	: 24/12/2020	Excess	: S\$0.00
Date of Inspection	: 23/12/2020	Est. Duration of Repair	: 20
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,979.13
Revised Amount	:S\$	17,406.73
Check Items (Estimated)	:S\$	6,290.40
Total	:S\$	23,697.13
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,500.00
COE / PARF Rebate	:S\$	43,037.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,463.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO REPAIR THE VEHICLE WITHIN \$17,000.00 ON LUMP SUM BASIS.