

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20014317/R1BA3Q2
Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100301878
Claimant
Vehicle No : SLG3727M **Insured Vehicle No :** SJD9992M
 Date of Loss: 19/12/2020 Nature of Claim: TP Claim No: 7742848008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG3727M**
 Make & Model: VOLKSWAGEN POLO, 1.2 TSI (A) Engine No: CJZA62826
 Reg. Date: 28/09/2016 (Man. Year: 2016) Chassis No: WVVZZZ6RZGU067210
 Colour: Red Odometer: 69502 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R16 Rear Tyre Size: 215/45 R16
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,102.48	4,807.86	294.62	5.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,850.00	6,650.00	5,200.00	43.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,952.48	11,457.86	5,494.62	32.41
+ GST 7.00/7.00% (S\$)	1,186.67	802.05	384.62	32.41
Nett Amount (S\$)	18,139.15	12,259.91	5,879.24	32.41
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Other Costs (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,891.91		

INSPECTION

Date of Assignment: 22/12/2020
 Date Inspected: 28/12/2020 Inspected At: VOLKSWAGEN GROUP
 SINGAPORE PTE LTD
 247 Alexandra Road
 Singapore 159934

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR RHF	Bent	1,604.45 FS	*1,604.45 FS
2	1		*DOOR SEAL OUTER BLACK RHF DOOR SEAL	Necessary	62.37 FS	*62.37 FS
3	4		*POP-RIVET	Necessary	4.56 FS	*4.56 FS
4	1		*DOOR RHR	Bent	1,604.45 FS	*1,604.45 FS
5	1		*DOOR SEAL OUTER BLACK RHR DOOR SEAL	Necessary	85.67 FS	*85.67 FS
6	2		*SOUND ABSORBER LAMINATED	Necessary	82.80 FS	*82.80 FS
7	1		*TAILLIGHT WITH REAR FOG L RHR	Repair	294.62 FS	*- FS
8	1		*RUBBER VALVE	Necessary	3.29 FS	*3.29 FS
9	1		*ALLOY WHEEL BLACK -GLOSSY	Scratched	1,360.27 FS	*1,360.27 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **5,102.48** **4,807.86**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNES REPAIR	New	280.00	0.00
3	WHEEL ALIGNMENT	New	360.00	360.00
4	WHEEL BALANCING	New	50.00	50.00
5	LABOUR	New	4,200.00	2,520.00
6	TRANSFER DOOR MECHANISM	New	1,680.00	840.00
7	SPRAY PAINTING	New	4,800.00	2,400.00
			Gross Labour Cost (\$\$)	11,850.00
				6,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >