

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDV 62H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR END PANEL (N) (CONSISTENT)	BENT	681.70	681.70
1	REAR END PANEL TOP GARNISH (N) (CONSISTENT)	MTG CRACKED	182.00	182.00
1	REAR BUMPER (N) (CONSISTENT)	BENT	746.00	746.00
2	REAR BUMPER SIDE RETAINER @\$37.90 (N) (CONSISTENT)	SERVICEABLE	75.80	-
2	REAR BUMPER REFLECTOR @\$68.90 (N) (CONSISTENT)	N/S CRACKED	137.80	68.90
1	REAR BUMPER TOW COVER (N) (CONSISTENT)	DENTED	45.90	45.90
1	REAR BUMPER REINFORCEMENT (N) (CONSISTENT)	BENT	246.10	246.10
1	REAR BUMPER TOP BEAM (N) (CONSISTENT)	DISTORTED	132.90	132.90
	LESS 10% DISCOUNT		-224.82	-210.35
			2,023.38	1,893.15
	SPECIAL NETT ITEMS			
2	REAR END PANEL TOP GARNISH CLIP @\$5.00 (SN) (CONSISTENT)	NECESSARY	10.00	10.00
10	REAR BUMPER CLIP @\$5.00 (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	CRACKED	350.00	200.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	DENTED	50.00	45.00
			460.00	305.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	15.00
	TO TUFF KOTE.		250.00	30.00
	TO REMOVE/REFIX UPHOLSTERY ,CUSHION SEAT & ROOF LINING .		150.00	60.00
	TO REMOVE /REFIX REVERSE SENSOR .		100.00	50.00
	TO PANEL BEATING ,REMOVING & REPLACING OF NEW PARTS.		1,000.00	500.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,000.00	450.00
			2,550.00	1,105.00
	GRAND TOTAL		5,033.38	3,303.15

Report Ref No. CC4/ASM20014319/Kga3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM20014319/Kga3q2

KONG SENG CHEONG

Licensed Appraiser