

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20014321/AGA3Q2
Date: 17/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMA5793C	Insured Vehicle No :	SHC1254S
Date of Loss:	21/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120409

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA5793C	Engine No:	2ZR0B77838
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU00J027983
Reg. Date:	13/06/2018 (Man. Year: 2018)	Odometer:	245641 km
Colour:	Green		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,704.94	2,090.92	1,614.02	43.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	900.00	920.00	50.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,524.94	2,990.92	2,534.02	45.87
Approved Total (Overridden) (S\$)		2,300.00		

(S\$)	5,524.94	2,300.00	3,224.94	58.37
+ GST 7.00/7.00% (S\$)	386.75	161.00	225.75	58.37
Nett Amount (S\$)	5,911.69	2,461.00	3,450.69	58.37
+ Loss of Use (4.0 x S\$40.00/day) (S\$)		160.00		
+ Car Rental (6.0 x S\$70.95/day) (S\$)		425.70		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,054.15		

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 28/12/2020

Inspected At:

N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2021)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA5793C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	523.90 FL	*523.90 FL
2	1		*REAR BUMPER END SEAL COVER RH	Not Necessary	92.30 FL	*- FL
3	1		*REAR BUMPER LOWER SPOILER	Deformed	325.00 FL	*325.00 FL
4	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	116.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	205.70 FL	*205.70 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET L/R	O/S Bent	279.20 FL	*139.60 FL
7	1		*REAR BUMPER SIDE RETAINER L/R	O/S Cracked	196.00 FL	*98.00 FL
8	1		*REAR BUMPER UNDER COVER	Deformed	179.00 FL	*179.00 FL
9	1		*REAR END PANEL	Repair	781.45 FL	*- FL
10	1		*REAR END PANEL ANTENNA SENSOR	Cracked	298.70 FL	*298.70 FL
11	1		*REAR TAILLAMP L/R	O/S Cracked	1,260.00 FL	*630.00 FL
12	1		*REAR TAILLAMP LOWER BRACKET L/R	O/S Cracked	136.00 FL	*68.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
14	1		*REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
15	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,803.25	2,707.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,098.31	616.98
Total Parts (\$\$)	3,704.94	2,090.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING (TO FR)	New	60.00	30.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	40.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	500.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	300.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	30.00
Gross Labour Cost (S\$)			1,820.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >