

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014322/APA3Q2

Date: 27/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMR592J	Insured Vehicle No :	SHD7142L
Date of Loss: 18/12/2020	Nature of Claim: TP	Claim No: MCT20120365

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR592J		
Make & Model:	KIA CERATO, 1.6 SUNROOF (A)	Engine No:	G4FGKH746501
Reg. Date:	17/12/2019 (Man. Year: 2019)	Chassis No:	KNAF5416MK5050808
Colour:	Blue	Odometer:	13958 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,857.53	2,823.28	4,034.25	58.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	1,700.00	2,700.00	61.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,257.53	4,523.28	6,734.25	59.82
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	11,257.53	3,600.00	7,657.53	68.02
+ GST 7.00/7.00% (\$\$)	788.03	252.00	536.03	68.02
Nett Amount (\$\$)	12,045.56	3,852.00	8,193.56	68.02
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
(\$\$)		4,212.00		
Liabile Amount (50.00%) (\$\$)		2,106.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,113.45		
Global Sum Settlement (\$\$)		2,100.00		

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 25/02/2021 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2021)
Parts:	143	KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR592J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR R/H DOOR	Repair	558.61 F	*- FL
2	2		*REAR R/H DOOR HINGE	Not Necessary	526.40 F	*- FL
3	1		*REAR R/H DOOR OUTER HANDLE	Not Necessary	51.88 F	*- FL
4	1		*REAR R/H DOOR OUTER HANDLE (SMALL)	Not Necessary	22.90 F	*- FL
5	2		*REAR R/H DOOR FRAME STICKER	Not Necessary	70.00 F	*- FL
6	1		*REAR R/H DOOR INNER RUBBER	Not Necessary	91.20 F	*- FL
7	1		*REAR R/H DOOR INNER TRIMBOARD	Not Necessary	514.50 F	*- FL
8	8		*REAR R/H DOOR INNER TRIMBOARD CLIP	Not Necessary	52.00 F	*- FL
9	1		*REAR R/H DOOR LOCK	Not Necessary	284.60 F	*- FL
10	1		*REAR R/H DOOR WINDOW REGULATOR MOTOR ASSY	Not Necessary	276.50 F	*- FL
11	1		*REAR R/H FENDER	Dented	1,349.63 F	*1,349.63 FL
12	1		*REAR R/H FENDER COWLING	Not Necessary	165.00 F	*- FL
13	10		*REAR R/H FENDER COWLING CLIP	Not Necessary	65.00 F	*- FL
14	1		*R/H SIDE SKIRT	Deformed	546.50 F	*546.50 FL
15	1		*REAR R/H RIM	Cut	926.16 FS	*400.00 FS
16	1		*REAR R/H TYRE	Not Necessary	350.00 F	*- FL
17	1		*REAR BUMPER	Deformed	786.65 F	*576.40 FL
18	1		*REAR BUMPER R/H SIDE RETAINER	Necessary	35.00 F	*35.00 FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	185.00 F	*185.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,857.53	3,092.53
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	269.25
Total Parts (\$\$)	6,857.53	2,823.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION	New	280.00	60.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	80.00
5	TO CHECK WIRING	New	100.00	30.00
6	TUFF KOTE	New	150.00	60.00
7	TOWING FEE	New	150.00	0.00
8	PANEL BEATING	New	1,800.00	500.00
9	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (\$)			4,400.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >