

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20014324/UGA3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900234555
Claimant Vehicle No :	SLP7663P	Insured Vehicle No :	SLE113P
Date of Loss:	19/12/2020	Nature of Claim:	TP
		Claim No:	7221200208SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7663P		
Make & Model:	DAIHATSU COPEN, 660cc (M)	Engine No:	JB0371872
Reg. Date:	21/11/2007 (Man. Year: 2007)	Chassis No:	L880K0041406
Colour:	Yellow	Odometer:	127668 km
Engine Capacity:	659 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/45 R15	Rear Tyre Size:	195/45 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,919.94	722.00	8,197.94	91.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	830.00	3,330.00	80.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,079.94	1,552.00	11,527.94	88.13
Approved Total (Overridden) (S\$)		1,200.00		

Nett Amount (S\$)	13,079.94	1,200.00	11,879.94	90.83
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,457.45		

INSPECTION

Date of Assignment: 24/12/2020

Date Inspected: 24/12/2020

Inspected At:

Nineteen Autowerks Pte Ltd (HQ)
 BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE
 Singapore 417808

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,382.50 FL	*- FL
2	1		*BOOTLID LOCK ASSY	Not Necessary	482.60 FL	*- FL
3	1		*BOOTLID LOCK CATCH	Not Necessary	120.00 FL	*- FL
4	2		*BOOTLID DAMPER	Not Necessary	373.00 FL	*- FL
5	2		*BOOTLID HINGE	Not Necessary	304.00 FL	*- FL
6	1		*BOOTLID WEATHERSTRIP	Not Necessary	226.40 FL	*- FL
7	2		*TAILLAMP	Not Necessary	905.00 FL	*- FL
8	1		*REAR BUMPER	Deformed / Torn	730.00 FL	*730.00 FL
9	2		*REAR BUMPER BRACKET	Not Necessary	145.00 FL	*- FL
10	2		*REAR BUMPER RETAINER	Not Necessary	131.20 FL	*- FL
11	2		*REAR BUMPER LAMP	Not Necessary	756.00 FL	*- FL
12	1		*REAR END PANEL PANEL	Repair	970.60 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	180.00 FL	*- FL
14	1		*SPARE TYRE PANEL	Not Necessary	1,220.00 FL	*- FL
15	1		*EXHAUST MUFFLER ASSY	Repair	996.00 FL	*- FL
16	2		*EXHAUST MOUNTING	Not Necessary	64.80 FL	*- FL
17	1		*SET REAR NUMBER PLATE LAMP	Not Necessary	129.50 FL	*- FL
18	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
19	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
20	1		*REAR NUMBER PLATE	Necessary	60.00 FS	*15.00 FS
21	2		*REVERSE SENSOR WITH MODULE	Not Necessary	300.00 FS	*- FS
22	2		*SET TAILLAMP CLIP	Not Necessary	70.00 FS	*- FS
23	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	45.00 FS	*- FS
24	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,831.60	795.00
- List Item Discount on L Items 10.00/10.00% (\$)	911.66	73.00
Total Parts (\$)	8,919.94	722.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AND STRENGTHEN PARTS ON REAR ACCIDENT AREA	New	1,800.00	300.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	20.00
3	R&R INTERIOR UPHOLSTERY	New	200.00	0.00
4	R&R BOOTLID COMPONENT	New	100.00	0.00
5	R&R EXHAUST PIPE ASSY	New	200.00	60.00
6	R&R REVERSE SENSOR AND TEST	New	80.00	50.00
7	TO APPLY UNDERCOATING FOR RUST ROOFING	New	200.00	0.00
8	SPRAY PAINTING ON REAR ACCIDENT AREA	New	1,500.00	400.00
Gross Labour Cost (\$\$)			4,160.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >