

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20014326/T1GA3Q2
Date: 17/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900091739
Claimant Vehicle No :	SHC153G	Insured Vehicle No :	SML4408P
Date of Loss:	21/12/2020	Nature of Claim:	TP
		Claim No:	8117225089SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC153G	Engine No:	G4LEKU297721
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU164638
Reg. Date:	02/07/2019 (Man. Year: 2019)	Odometer:	120191 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,571.88	1,037.36	3,534.52	77.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	910.00	510.00	35.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,991.88	1,947.36	4,044.52	67.50
+ GST 7.00/7.00% (S\$)	419.43	136.32	283.11	67.50

Nett Amount (S\$)	6,411.31	2,083.68	4,327.63	67.50
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
(S\$)		2,784.44		
Liabe Amount (50.00%) (S\$)		1,392.22		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,394.22		
Global Sum Settlement (S\$)		1,390.00		

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 22/12/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cracked	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER GRILLE LH	Cracked	186.90 FL	*186.90 FL
3	1		*FRONT DAYLIGHT LH	Not Necessary	642.50 FL	*- FL
4	1		*FRONT BUMPER BRACKET LH	Not Necessary	35.00 FL	*- FL
5	1		*HEADLAMP ASSY LH	Not Necessary	1,993.65 FL	*- FL
6	1		*HEAD SUPPORT PANEL	Not Necessary	949.30 FL	*- FL
7	1		*FRONT BUMPER CTR MOULDING	Not Necessary	186.90 FL	*- FL
8	1		*FRONT LH FENDER	Repair	588.80 FL	*- FL
9	1		*FRONT FENDER SHIELD LH	Torn	164.70 FL	*164.70 FL
10	1		*FENDER EMBLEM BLUE-DRIVE	Necessary	26.60 FL	*26.60 FL
11	1		*FRONT LH WHEEL COVER	Cut	346.40 FL	*346.40 FL
12	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
13	1		*DUCT ASSY	Deformed	153.80 FL	*153.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

5,714.85

1,296.70

- List Item Discount on L Items 20.00/20.00% (S\$)

1,142.97

259.34

Total Parts (S\$)

4,571.88

1,037.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	480.00
2	SPRAY PAINTING	New	600.00	400.00
3	CHECK LIGHTING	New	60.00	0.00
4	REMOVE/REFIX A/C CONDENSER & CHARGE GAS	New	60.00	30.00
Gross Labour Cost (S\$)			1,420.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >