PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: M/s Voulez Cars

c/o 53 Ubi Ave 1, Paya Ubi Industrial Park

Date Our Ref : 02nd December 2020

Policy No

: PS/011/11/20

#05-44

Singapore 408934

Sum Insured

Excess

: T/P Claim

Assigned By

: M/s Voulez Cars

Assignment Date Accident Date

: 27th November 2020 : 15th November 2020 : 27th November 2020

Inspection Date Workshop Name

: Neo Automotive Pte Ltd

Survey Conducted At

: 53 Ubi Ave 1, Paya Ubi Industrial Park

#05-44

Singapore 408934

PARTICULARS OF VEHICLE

Registration No

: SLG 0375 P

Mileage

: 193603km

Make/Model

: Toyota Axio

Engine No

: HIDDEN

Type Of Body

: Motorcar

Chassis No

: NRE161-0020922

Year Of Manu./Regn. : 2016

Passenger Cap. : 4 Passengers

Colour

: Met. Blue

Others

CONDITION OF TYRES

R/H SIDE

L/H SIDE

Front Tyre

: 6mm 185/60R15 Arivo

6mm 185/60R15 Arivo

Rear Tyre

: 6mm 185/60R15 Arivo

6mm 185/60R15 Arivo

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake

: Serviceable

Body Work

: Good

Footbrake

: Serviceable

Paint Work

: Good

Steering

: Serviceable

Others

. -

POINT OF IMPACT

The vehicle sustained an impact on the L/H rear portion.

GENERAL DESCRIPTION OF DAMAGES

The L/H doors, door centre pillar were dented/distorted.

For details of damages please refer to schedule attached.

REMARKS:

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No: SLG 0375 P				Our Ref:	PS	S/011/11/20
Otv	Descriptions	Conditions		Repairer's Est.	(Our Revised.
Qty 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	LIST ITEMS L/H rear door L/H rear door glass outer moulding L/H rear door weatherstrip L/H rear door lock L/H rear door regulator gear L/H rear door regulator gear motor L/H rear door outer handle L/H rear door inner trimboard L/H rear door hinge L/H rear door stricker L/H rear door glass channel L/H rear door glass channel L/H rear door glass channel rubber L/H door centre pillar	dented/distorted necessary distorted dented dented	\$ 1558 1168	1,220.10 190.85 210.21 578.55 219.95 388.45 291.65 425.00	\$	1,220.10 190.85 210.21 578.55 219.95 388.45 186.60 186.20 86.40 88.90 65.10
1		dented - repair Less 25%	% \$	698.50 4,836.46 4,836.46	\$	3,421.31 855.33 2,565.98
	Labour Charges & Misc To dismantle & replace damaged parts, panel beat where necessary.			700.00		450.00 500 600.00 500 80.0050
	To putty, apply primer & spray-paint on the affected portion.			800.00		600.00
	To apply rust-proofing on repaired, replaced panel. To remove/transfer L/H rear door components.		106	120.00		89,865
				100.00		80.00
	To check wiring functions.		\$	100.00	\$ _	70.00 30 3,845.98
			total: 2228.65			

Note: The repairer has agreed to undertake the repairs at our adjusted amount of \$3,100.00 lump sum corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FOUR (4)** days.
Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES

1750 04 Days

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer