6/10/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20014327/KBA3Q2

Date:

10/06/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2100464735 SLC2487H

Engine No:

Chassis No:

Odometer:

Claimant Vehicle No:

SMT9201T 17/12/2020 Insured Vehicle No: Nature of Claim:

TP

Claim No:

3526869507SG

WVWZZZAUZGW231006

CZC087811

75841 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMT9201T

Make & Model: VOLKSWAGEN GOLF, 1.2 TSI (A)

Reg. Date: 26/08/2016 (Man. Year: 2016)

Colour: Metallic Grey

**Engine Capacity:** 1395 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

**Engine Modification:** Yes

No

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Right Side:

Front Tyre Size: Front Left Side:

225/40Z R18 Michelin 6 mm

Michelin 6 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 225/40Z R18 Michelin 6 mm

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		600.00	300.00	300.00	50.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	600.00	300.00	300.00	50.00
	+ GST 7.00/7.00% (S\$)	42.00	21.00	21.00	50.00

Nett Amount (S\$)	642.00	321.00	321.00	50.00
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	423.00		

**INSPECTION** 

Date of Assignment: 22/12/2020

Alan's United Auto Pte Ltd (HQ)

Blk 7 Sin Ming Industrial Estate, #01-76 Date Inspected: Inspected At: 01/03/2021

Singapore 575642

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly

# **REPAIR DETAILS**

## **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPAIR ,ADJUST ,ALIGN AND TO REFIX REAR BUMPER	New	200.00	100.00
2	TO PUTTY AND SPRAY REAR BUMPER	New	200.00	200.00
3	TO REPAIR REAR RH SPORT RIM	New	200.00	0.00
		Gross Labour Cost (S\$)	600.00	300.00
	Report was unsubmitted	during this print-out.		

< END OF ESTIMATES >