11/17/21, 3:34 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014328/T1GA3Q2

17/11/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900104617 **Claimant Vehicle**

SHD3284L Insured Vehicle No: SGS2118Z No:

Date of Loss: 18/12/2020 Nature of Claim: TP Claim No: 9381930603SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3284L

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDEU419929

Reg. Date: KMHLB41UMGU091879 08/07/2016 (Man. Year: 2016) Chassis No:

Colour: Odometer: 658123 km Blue

Engine Capacity: 1685 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		934.56	0.00	934.56	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		930.00	480.00	450.00	48.39
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,864.56	480.00	1,384.56	74.26
	+ GST 7.00/7.00% (S\$)	130.52	33.60	96.92	74.26
	Nett Amount (S\$)	1,995.08	513.60	1,481.48	74.26
	+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	+ Car Rental (3.0 x S	S\$114.95/day) (S\$)	344.85		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,010.45		
	Global Su	m Settlement (S\$)	1,000.00		

INSPECTION

Date of Assignment: 22/12/2020

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 22/12/2020 Inspected At:

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Chong Pui Lin Adjuster: MOHD TAUFIKH BIN HAMID Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	1,052.20 FL	*- FL
2	10		*BUMPER CLIP	Not Necessary	22.00 FL	*- FL
3	1		*FRONT BUMPER BRACKET TOP LH	Not Necessary	44.80 FL	*- FL
4	1		*FRONT BUMPER BRACKET SIDE LH	Not Necessary	49.20 FL	*- FL
F=Fra	nchise	part. L=ListIte	mDisc.			
				Sub Total (S\$)	1,168.20	0.00
			- List Item Discount on L	Items 20.00/20.00% (S\$)	233.64	0.00
				Total Parts (S\$)	934.56	0.00
			Report was unsubmitted durin	a this print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	480.00	280.00
2	SPRAY PAINTING	New	400.00	200.00
3	CHECK LIGHTING	New	50.00	0.00
		Gross Labour Cost (S\$)	930.00	480.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >