

REPAIR ESTIMATE*

VEHICLE NO SHD3284L

DATE 18.12.20

MAKE :

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		Rp	\$1,052.20
10	BUMPER CLIP		nn X	\$22.00
1	FRONT BUMPER BRACKET TOP LH/		nn X	\$44.80
1	FRONT BUMPER BRACKET SIDE /LH		nn X	\$49.20
SUB TOTAL				\$1,168.20
20.00%				\$233.64
				\$934.56
Labour Charge				
Panel Beating				280 \$480.00
Spray painting				200 \$400.00
Check lighting				NN X \$50.00
				\$930.00
ESTIMATE TOTAL				\$1,864.56
				\$480
				# 2days
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpin 93495749 w/lahe
 up 22/12/20 4pm
 2days
 Resurvey after repair
 Tanpin @/khanb-wm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: