

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014330/APA3Q2
Date: 12/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800100543	
Claimant Vehicle No : SKT2836G	Insured Vehicle No : SKT7637G	
Date of Loss: 18/12/2020	Nature of Claim: TP	Claim No: 3572386773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT2836G		
Make & Model: SUBARU XV, 1.6 I-S AWD CVT (A)	Engine No: FB161645629	
Reg. Date: 29/05/2015 (Man. Year: 2015)	Chassis No: JF1GP3KC5FG151034	
Colour: Grey	Odometer: 145856 km	
Engine Capacity: 1600 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17	Rear Tyre Size: 225/55 R17	
Front Left Side: Bridgestone 6 mm	Rear Left Side: Bridgestone 6 mm	
Front Right Side: Bridgestone 6 mm	Rear Right Side: Bridgestone 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,121.00	11,601.44	8,519.56	42.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	4,020.00	3,480.00	46.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,621.00	15,621.44	11,999.56	43.44
Approved Total (Overridden) (\$\$)		12,500.00		
Nett Amount (\$\$)	27,621.00	12,500.00	15,121.00	54.74
+ Car Rental (16.0 x S\$100.00/day) (\$\$)		1,600.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		14,107.45		
Global Sum Settlement (\$\$)		13,800.00		

INSPECTION

Date of Assignment: 22/12/2020		
Date Inspected: 22/12/2020	Inspected At:	Trident Auto Service Centre Pte Ltd (HQ) 8 Kaki bukit Ave 4 #02-44 Premier Singapore 415875
Estimated Period of Repair: 15.0 days		

5/12/2021

Adjuster Report

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,386.50 FL	*1,160.60 FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	263.90 FL	*- FL
3	1		*TAILGATE LOGO	Not Necessary	89.20 FL	*- FL
4	1		*TAILGATE SUBARU EMBLEM	Necessary	77.90 FL	*77.90 FL
5	1		*TAILGATE XV EMBLEM	Necessary	69.80 FL	*69.80 FL
6	1		*TAILGATE AWD EMBLEM	Necessary	81.90 FL	*81.90 FL
7	1		*TAILGATE LOCK	Jammed	324.80 FL	*270.00 FL
8	1		*TAILGATE LOCK SENSOR	Damaged	414.20 FL	*177.00 FL
9	1		*TAILGATE LOCK SENSOR BRACKET	Bent	58.90 FL	*23.00 FL
10	1		*TAILGATE LOCK CATCH	Not Necessary	109.60 FL	*- FL
11	1		*TAILGATE W/STRIPE	Cut	299.60 FL	*299.60 FL
12	1		*TAILGATE INNER TRIM BOARD	Cracked	693.20 FL	*353.00 FL
13	1		*TAILGATE ABSORBER LH	Not Necessary	200.30 FL	*- FL
14	1		*TAILGATE ABSORBER RH	Not Necessary	200.30 FL	*- FL
15	1		*REAR W/SCREEN MOULDING TOP	Necessary	95.20 FL	*40.00 FL
16	1		*REAR W/SCREEN MOULDING BOTTOM	Necessary	90.40 FL	*40.00 FL
17	1		*REAR W/SCREEN MOULDING LH	Necessary	81.70 FL	*30.00 FL
18	1		*REAR W/SCREEN MOULDING RH	Necessary	81.70 FL	*30.00 FL
19	1		*TAILLAMP LH	Cracked	577.40 FL	*482.00 FL
20	1		*TAILLAMP RH	Cracked	577.40 FL	*482.00 FL
21	1		*TAILLAMP CLIP LH	Necessary	13.90 FL	*13.90 FL
22	1		*TAILLAMP CLIP RH	Necessary	13.90 FL	*13.90 FL
23	1		*TAILLAMP RETAINER LH	Damaged	79.40 FL	*35.00 FL
24	1		*TAILLAMP RETAINER RH	Damaged	79.40 FL	*35.00 FL
25	1		*TAILLAMP PANEL LH	Repair	289.10 FL	*- FL
26	1		*TAILLAMP PANEL RH	Repair	289.10 FL	*- FL
27	1		*REAR BUMPER	Distorted	894.50 FL	*782.00 FL
28	1		*REAR BUMPER REINFORCEMENT	Bent	699.20 FL	*497.00 FL
29	1		*REAR BUMPER BRACKET LH	Not Necessary	87.90 FL	*- FL
30	1		*REAR BUMPER BRACKET RH	Not Necessary	87.90 FL	*- FL
31	1		*REAR BUMPER SIDE RETAINER LH	Necessary	98.50 FL	*36.00 FL
32	1		*REAR BUMPER SIDE RETAINER RH	Necessary	98.50 FL	*36.00 FL
33	1		*REAR BUMPER REFLECTOR CENTER	Cracked	111.60 FL	*111.60 FL
34	1		*REAR BUMPER TOW COVER	Missing	51.90 FL	*51.90 FL
35	1		*REAR END PANEL	Distorted	521.80 FL	*521.80 FL
36	1		*REAR END PANEL TOP GARNISH	Deformed	225.40 FL	*225.40 FL
37	1		*SPARE WHEEL PANEL	Buckled	659.30 FL	*659.30 FL
38	1		*REAR FENDER INNER TRIM BOARD LH	Cracked	793.10 FL	*497.60 FL
39	1		*REAR EXHAUST BOX	Dented	1,289.30 FL	*980.00 FL
40	1		*REAR EXHAUST BOX HEAT SHIELD	Crumpled	472.80 FL	*78.30 FL
41	2		*REAR EXHAUST BOX MOUNTING	Not Necessary	88.20 FL	*- FL
42	1		*REAR EXHAUST BOX GASKET	Necessary	45.60 FL	*45.60 FL
43	1		*BONNET LOCK	Not Necessary	156.90 FL	*- FL
44	1		*H/LAMP LH	Cracked	1,359.80 FL	*1,359.80 FL
45	1		*H/LAMP RH	Cracked	1,359.80 FL	*1,359.80 FL
46	1		*H/LAMP RETAINER LH	Cracked	188.40 FL	*48.00 FL
47	1		*H/LAMP RETAINER RH	Cracked	188.40 FL	*48.00 FL
48	1		*RADIATOR GRILLE	Cracked	946.20 FL	*482.00 FL
49	1		*RADIATOR GRILLE LOGO	Necessary	89.20 FL	*89.20 FL
50	1		*RADIATOR GRILLE CHROME	Cut	268.90 FL	*268.90 FL
51	1		*RADIATOR GRILLE CHROME CENTER	Not Necessary	145.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT BUMPER	Deformed	894.20 FL	*759.00 FL
53	1		*FRONT BUMPER SPONGE	Cracked	237.40 FL	*115.00 FL
54	1		*FRONT BUMPER REINFORCEMENT	Bent	717.50 FL	*488.00 FL
55	1		*FRONT BUMPER BRACKET LH	Not Necessary	92.10 FL	*- FL
56	1		*FRONT BUMPER BRACKET RH	Not Necessary	92.10 FL	*- FL
57	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	100.80 FL	*36.00 FL
58	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	100.80 FL	*36.00 FL
59	1		*FRONT BUMPER TOW COVER	Not Necessary	51.90 FL	*- FL
60	1		*FRONT SUPPORT PANEL	Not Necessary	645.80 FL	*- FL
61	1		*FRONT BRACE PANEL	Not Necessary	89.80 FL	*- FL
62	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
63	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
64	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
65	1		*SET REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
66	1		*SET REAR W/SCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
67	1		*SET REAR W/SCREEN INNER SEAL	Necessary	40.00 FS	*30.00 FS
68	1		*SET REVERSE CAMERA	Damaged	300.00 FS	*300.00 FS
69	1		*SET REAR FENDER INNER TRIM BOARD CLIPS LH	Necessary	100.00 FS	*30.00 FS
70	1		*SET REAR FENDER INNER TRIM BOARD CLIPS RH	Necessary	100.00 FS	*30.00 FS
71	1		*SET REAR FENDER INNER SHIELD CLIPS LH	Not Necessary	40.00 FS	*- FS
72	1		*SET REAR FENDER INNER SHIELD CLIPS RH	Not Necessary	40.00 FS	*- FS
73	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
74	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
75	1		*SET REAR NO.PLATE WITH HOLDER	Dented	60.00 FS	*60.00 FS
76	1		*SET SPARE WHEEL PANEL INSULATION	Not Necessary	100.00 FS	*- FS
77	1		*SET TAILLAMP PANEL SEALANT LH	Not Necessary	60.00 FS	*- FS
78	1		*SET TAILLAMP PANEL SEALANT RH	Not Necessary	60.00 FS	*- FS
79	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
80	1		*SET FRONT NO.PLATE WITH HOLDER	Dented	60.00 FS	*60.00 FS
81	1		*SET RADIATOR GRILLE CLIPS	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,170.00	14,266.80
- List Item Discount on L Items 10.00/20.00% (S\$)	2,049.00	2,665.36
Total Parts (S\$)	20,121.00	11,601.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT ,WELD REAR END PANEL ,TAILLAMP PANEL ,TO REPLACE TAILGATE ASSY ,REPAIR SPARE WHEEL PANEL ,BOTH REAR CHASSIS MEMBER AND RE-ALIGN ON ALL ACCIDENT AFFECTED AREAS	New	2,000.00	1,400.00
2	TO PUTTY AND RESPRAY ON REAR ACCIDENT PORTION	New	1,800.00	1,300.00
3	TO CHECK REAR LIGHTING AND WIRING	New	100.00	30.00
4	TO APPLY ANTI -RUST CORROSION ON REAR AFFECTED AREAS	New	200.00	80.00
5	TO REMOVE AND REFIT REAR W/SCREEN	New	200.00	120.00
6	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	New	200.00	80.00
7	TO REMOVE AND REFIT UPHOLSTERY ,LINING ,GARNISH ETC TO FACILITATE REPAIR	New	400.00	250.00
8	TO DO COMPUTERISED WHEEL ALIGNMENT	New	200.00	0.00
9	TO REMOVE AND REPLACE REAR EXHAUST SYSTEM	New	200.00	80.00
10	TO REPLACE FRONT BUMPER ,FRONT REINFORCEMENT ,RADIATOR GRILLE,TO REPAIR FRONT SUPPORT PANEL ,BOTH FRONT CHASSIS EXTENSION AND REALIGN ON ALL ACCIDENT AFFECTED AREAS	New	1,000.00	400.00
11	TO PUTTY AND RESPRAY ON FRONT ACCIDENT PORTION	New	800.00	250.00
12	TO CHECK FRONT LIGHTING AND WIRING	New	100.00	30.00
13	TO APPLY ANTI-RUST CORROSION ON FRONT AFFECTED AREAS	New	100.00	0.00
14	TO REMOVE AND REFIT ACON CONDENSER ,RADIATOR ASSY PLUS VACUUM AND TOP UP ACON GAS ETC TO ASSIST REPAIR	New	200.00	0.00
Gross Labour Cost (\$\$)			7,500.00	4,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >