

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III20014331/KGA3Q2

Date:

17/06/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : SHD403E**Insured Vehicle No :**

GBH396S

Date of Loss: 19/12/2020

Nature of Claim:

TP

Claim No:

MFL2020D0002815

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD403E**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No:

M9R8839C003244

Reg. Date: 17/10/2016 (Man. Year: 2016)

Chassis No:

VF1ABL15AUC283430

Colour: Metallic White/Red

Odometer:

524103 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: 9 mm

Rear Left Side:

7 mm

Front Right Side: 9 mm

Rear Right Side:

7 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,518.32	10,200.59	6,317.73	38.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	4,120.00	3,760.00	47.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,398.32	14,320.59	10,077.73	41.31
Approved Total (Overridden) (S\$)		11,450.00		

(S\$)	24,398.32	11,450.00	12,948.32	53.07
+ GST 7.00/7.00% (S\$)	1,707.88	801.50	906.38	53.07
Nett Amount (S\$)	26,106.20	12,251.50	13,854.70	53.07
+ Loss of Use (13.0 x S\$40.00/day) (S\$)		520.00		
+ Car Rental (13.0 x S\$81.13/day) (S\$)		1,054.69		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,833.64		

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 22/12/2020

Estimated Period of Repair: 12.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2021)
Parts:	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD403E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Bent / Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
4	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
5	1		*BUMPER BRACKET CTR REAR	Distorted	98.10 FL	*98.10 FL
6	1		*BUMPER BRACKET SIDE RH REAR	Distorted	82.10 FL	*82.10 FL
7	1		*BUMPE RETAINER RH REAR	Distorted	59.80 FL	*59.80 FL
8	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
9	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
10	1		*ABSORBER REAR	No such part	217.30 FL	*- FL
11	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
12	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	*114.50 FL
13	1		*BUMPER BEAM BRACKET RH REAR	Bent	114.50 FL	*114.50 FL
14	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
15	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
16	1		*FENDER PANEL REAR RH	Buckled	1,933.20 FL	*1,933.20 FL
17	1		*FENDER PANEL INNER FRT RH	Serviceable	838.40 FL	*- FL
18	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
19	1		*FENDER PANEL REAR LH	Buckled	1,933.20 FL	*1,933.20 FL
20	1		*FENDER PANEL INNER FRT RH	Serviceable	838.40 FL	*- FL
21	1		*WHEELARCH FRT LH	Serviceable	191.40 FL	*- FL
22	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
23	1		*TAILLAMP RH	Cracked	401.40 FL	*401.40 FL
24	1		*TAILLAMP LH	Cracked	401.40 FL	*401.40 FL
25	1		*EXHAUST CAP REAR	Dented	125.40 FL	*125.40 FL
26	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
27	1		*BOOT WEATHERSTRIP (50%)	Distorted / Dented	160.38 FS	*89.10 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	*277.70 FL
29	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	*277.70 FL
30	1		*BOOT HINGE LH	Serviceable	254.20 FL	*- FL
31	1		*BOOT HINGE RH	Serviceable	254.20 FL	*- FL
32	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
33	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
34	1		*BOOT LOCK	Jammed	246.60 FL	*246.60 FL
35	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
36	1		*BOOT FINISHER	Cracked	344.70 FL	*344.70 FL
37	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
38	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
39	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
40	1		*SPARE WHEEL PANEL	Serviceable	1,229.40 FL	*- FL
41	1		*SET PARKING AID	Dented / Shorted	700.00 FS	*400.00 FS
42	1		*SET FENDER CLIP	Not Necessary	65.00 FS	*- FS
43	1		*SET FENDER LINER CLIP	Not Necessary	60.00 FS	*- FS
44	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
45	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
46	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
47	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
48	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
49	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
50	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
51	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
52	1		*BUMPER CLIP FRT	Not Necessary	85.00 FS	*- FS
53	1		*BUMPER RETAINER CLIP FRT	Not Necessary	70.00 FS	*- FS
54	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	70.00 FS	*- FS
55	1		*LICENSE PLATE WITH HOLDER FRT	Serviceable	120.00 FS	*- FS
56	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
57	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
58	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,125.56	11,257.20
- List Item Discount on L Items 10.00/10.00% (\$)	1,607.24	1,056.61
Total Parts (\$)	16,518.32	10,200.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	120.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	1,540.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	2,000.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	120.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	80.00
8	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	120.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			7,880.00	4,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >