

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20014339/UTF3Q2

Date: 08/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant
Vehicle No : FBN1742M

Insured Vehicle No : SHC2885P

Date of Loss: 17/12/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN1742M**

Make & Model: YAMAHA SNIPER T150, 150cc

Engine No: G3E6E0405344

Reg. Date: 24/07/2018 (Man. Year: 2018)

Chassis No: MH3UG0740J0111403

Colour: Green

Odometer: 25136 km

Engine Capacity: 150 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70-90-17

Rear Tyre Size: 120-70-17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,103.20	3,199.50	4,903.70	60.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	580.00	3,070.00	84.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	11,753.20	3,779.50	7,973.70	67.84
Approved Total (Overridden) (\$)		3,000.00		
Nett Amount (\$)	11,753.20	3,000.00	8,753.20	74.48

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 24/12/2020 Inspected At:

Euro Success Services Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 #02-03

AUTOBAY

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jan 2021)	
Parts:	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN1742M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent/Twisted	180.00 FL	*166.00 FL
2	1		*HANDLE BALANCER O/S	Scratched	40.00 FL	*40.00 FL
3	2		*THROTTLE CABLE	Not Necessary	100.00 FL	*- FL
4	1		*MIRROR L-R	O/s Broken	400.00 FL	*80.00 FL
5	1		*BRAKE LEVER	Scratched	98.00 FL	*62.00 FL
6	1		*HEAD LAMP	Not Necessary	850.00 FL	*- FL
7	1		*SET FORK TUBE }	Bent/Twisted	720.00 FL	*680.00 FL
8	2		*FORK OILSEAL }		70.00 FL	*- FL
9	1		*RIM SHAFT	Bent	75.00 FL	*42.00 FL
10	1		*FRONT FAIRING INNER	Cracked	750.00 FL	*215.00 FL
11	1		*FRONT DISC	Bent	350.00 FL	*222.00 FL
12	1		*STEERING CONE BEARING	Necessary	85.00 FL	*80.00 FL
13	1		*STEEM STEERING	Not Necessary	105.00 FL	*- FL
14	2		*FRONT SIGNAL L-R	Cracked	170.00 FL	*170.00 FL
15	1		*HEAD LAMP COVER	Cracked	350.00 FL	*188.00 FL
16	1		*METER	Not Necessary	450.00 FL	*- FL
17	1		*FRONT FENDER	Cracked	150.00 FL	*145.00 FL
18	1		*TANK COVER	No such part	180.00 FL	*- FL
19	1		*FRONT BODY COVER R/H	Cracked	350.00 FL	*315.00 FL
20	1		*FRONT BODY LOWER COVER R/H	Cracked	200.00 FL	*180.00 FL
21	1		*GEAR PEDAL	Not Necessary	105.00 FL	*- FL
22	1		*FRONT FOOT REST R/H	Cut	55.00 FL	*55.00 FL
23	1		*REAR FOOT REST R/H	Cut	65.00 FL	*65.00 FL
24	1		*SEAT COVER R/H	Cracked	185.00 FL	*185.00 FL
25	1		*L BAR	Not Necessary	110.00 FL	*- FL
26	2		*REAR SIGNAL L-R	Not Necessary	175.00 FL	*- FL
27	1		*FRONT TYRE	Not Necessary	200.00 FL	*- FL
28	1		*FRONT BRAKE PUMP	Not Necessary	400.00 FL	*- FL
29	1		*BASKET COVER	Cracked	100.00 FL	*60.00 FL
30	1		*IU UNIT	Not Necessary	180.00 FL	*- FL
31	1		*EXHAUST	Dented	850.00 FL	*490.00 FL
32	1		*EXHAUST COVER	Scratched	350.00 FL	*115.00 FL
33	1		*FRONT SPORT RIM	Repair	300.00 FS	*- FS
34	1		*FRONT TYRE	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,948.00	3,555.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	844.80	355.50
Total Parts (\$\$)	8,103.20	3,199.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORTATION CHARGES	New	250.00	30.00
2	TO RESPRAY PAINTING AND ETC	New	1,300.00	250.00
3	TO CHECK FRONT AND REAR ELECTRICAL WIRING	New	100.00	0.00
4	TO REMOVE,REFIX AND REALIGN FRONT FORK	New	300.00	0.00
5	PANEL BEATING,CUT,WELD REMOVE AND REPLACE ABOVE PARTS }	New	1,200.00	300.00
6	TO STRAIGHTEN,REPAIR AND REALIGN CHASSIS FRAME MEMBER }	New	500.00	0.00
Gross Labour Cost (\$\$)			3,650.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >