

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20014362/EVD3E2
Date: 14/01/2021

REFERENCE

Insured/Claimant: KOK LAN CHOO Policy No: 2070061512
Date of Loss: 22/12/2020 Nature of Claim: OD Claim No: 3520852780SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT2709S**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH739818
Reg. Date: 03/04/2020 (Man. Year: 2019) Chassis No: KNAF5416ML5060347
Colour: Blue Odometer: 21019 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Nexen 5 mm Rear Left Side: Nexen 5 mm
Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,359.60	6,492.00	2,867.60	30.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,780.00	3,870.00	910.00	19.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,139.60	10,362.00	3,777.60	26.72
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	13,839.60	10,062.00	3,777.60	27.30
+ GST 7.00/7.00% (S\$)	968.77	704.34	264.43	27.30
Nett Amount (S\$)	14,808.37	10,766.34	4,042.03	27.30

INSPECTION

Date of Assignment: 23/12/2020
Date Inspected: 23/12/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
3	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
4	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
5	1		*GUARD-AIR, LH	Not Necessary	28.00 FL	*- FL
6	1		*GUARD-AIR, RH	Crushed	28.00 FL	*28.00 FL
7	1		*CONDENSER ASSY-COOLER	Bent	687.00 FL	*687.00 FL
8	1		*RADIATOR ASSY	Not Necessary	646.00 FL	*- FL
9	1		*BLOWER ASSY	Not Necessary	656.00 FL	*- FL
10	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
13	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
14	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	14.00 FL	*- FL
15	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	14.00 FL	*- FL
16	1		*LAMP ASSY-SIDE REPEATER, LH	Not Necessary	143.00 FL	*- FL
17	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 FL	*143.00 FL
18	1		*MOULDING-FRONT BUMPER, LH	Broken	216.00 FL	*216.00 FL
19	1		*MOULDING-FRONT BUMPER, RH	Broken	216.00 FL	*216.00 FL
20	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
21	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
22	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
23	1		*CAP-FRONT HOOK	Missing	9.00 FL	*9.00 FL
24	1		*GRILLE-FRONT BUMPER	Broken	485.00 FL	*485.00 FL
25	1		*COVER-FR BUMPER FOG LAMP, LH	Not Necessary	15.00 FL	*- FL
26	1		*COVER-FR BUMPER FOG LAMP, RH	Not Necessary	15.00 FL	*- FL
27	2		*RETAINER-BUMPER SIDE MTG	Necessary	2.00 FL	*2.00 FL
28	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	303.00 FL	*- FL
29	1		*LAMP ASSY-FRONT FOG, RH	Not Necessary	303.00 FL	*- FL
30	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
31	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
32	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
33	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	163.00 FL	*- FL
34	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
35	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
36	1		*HINGE ASSY-HOOD, RH	Bent	43.00 FL	*43.00 FL
37	1		*HINGE ASSY-HOOD, LH	Bent	43.00 FL	*43.00 FL
38	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
39	1		*PAD-HOOD INSULATING	Crushed	156.00 FL	*156.00 FL
40	1		*LATCH ASSY-HOOD	Not Necessary	103.00 FL	*- FL
41	1		*HORN ASSY-LOW PITCH	Broken	74.00 FL	*74.00 FL
42	1		*LAMP ASSY-HEAD,RH (Supplementary)	Broken	2,210.00 FL	*2,210.00 FL
43	10		*CLIP-SIDE GARNISH MTG (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,687.00	8,110.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,327.40	1,618.00
Total Parts (\$\$)	9,359.60	6,492.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER, REPAIR RH FRONT DOOR PANEL, REPAIR LH FRONT FENDER	New	2,000.00	1,600.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	100.00
3	TOP UP A/CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	REMOVE AND INSTALLL PARKING ASSIST	New	60.00	60.00
5	PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR, LH FRONT FENDER AND AFFECTED PORTION	New	2,100.00	1,750.00
6	APPLY BODY SEALANT	New	120.00	40.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	PERFORM RUST PREVENTION	New	120.00	40.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
Gross Labour Cost (S\$)			4,780.00	3,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >