

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20014367/AQD3Q2

Date: 05/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100378483
Claimant		
Vehicle No : SLD5556S	Insured Vehicle No :	SKN6982Y
Date of Loss: 22/12/2020	Nature of Claim: TP	Claim No: 2290300687SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD5556S		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	1ZRX578679
Reg. Date:	22/06/2016 (Man. Year: 2016)	Chassis No:	MR053REH104552275
Colour:	Silver	Odometer:	164726 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,431.98	6,763.16	8,668.82	56.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,380.00	1,950.00	45.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,761.98	9,143.16	10,618.82	53.73
Approved Total (Overridden) (\$\$)		7,300.00		
Nett Amount (\$\$)	19,761.98	7,300.00	12,461.98	63.06

INSPECTION

Date of Assignment:	23/12/2020	
Date Inspected:	23/12/2020 Inspected At:	Jippun Trading (kaki Bukit) (HQ) 1 KAKI BUKIT AVE 6# 02-11 AUTOBAY Singapore 417883
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	581.80 FL	*581.80 FL
2	1		*FRONT BUMPER FOG LAMP-LH	Not Necessary	377.45 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP COVER	Cut	121.50 FL	*121.50 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	140.63 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	477.73 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINERS-L/R	N/s Damaged	97.70 FL	*48.85 FL
7	1		*FRONT BONNET	Not Necessary	1,140.45 FL	*- FL
8	1		*FRONT FENDER-LH	Distorted	731.35 FL	*731.35 FL
9	1		*FRONT FENDER EMBLEM VVT-I	Necessary	42.20 FL	*42.20 FL
10	1		*FRONT FENDER INNER SHIELD	Torn	141.43 FL	*141.43 FL
11	1		*FRONT FENDER BRACKET	Distorted	89.65 FL	*89.65 FL
12	1		*FRONT FENDER WHEEL HOUSING	Repair	510.60 FL	*- FL
13	1		*FRONT DOOR-LH	Dented	1,257.60 FL	*1,257.60 FL
14	1		*FRONT DOOR OUTER HANDLE	Not Necessary	181.90 FL	*- FL
15	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	141.20 FL	*- FL
16	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	163.56 FL	*- FL
17	1		*FRONT DOOR GLASS REGULATOR	Not Necessary	291.65 FL	*- FL
18	1		*FRONT DOOR INSULATION	Not Necessary	130.20 FL	*- FL
19	1		*FRONT DOOR W/STRIP	Not Necessary	181.92 FL	*- FL
20	1		*FRONT DOOR INNER LOCK	Not Necessary	481.95 FL	*- FL
21	1		*FRONT DOOR CHECKER	Not Necessary	89.95 FL	*- FL
22	1		*FRONT SHOCK ABSORBER-LH	Bent	481.95 FL	*481.95 FL
23	1		*FRONT SHOCK ABSORBER TOP MOUNT	Not Necessary	156.85 FL	*- FL
24	1		*FRONT LOWER ARM	Bent	640.50 FL	*459.00 FL
25	1		*FRONT LOWER ARM BALL JOINT	Not Necessary	210.30 FL	*- FL
26	1		*FRONT KNUCKLE ARM	Damaged	556.20 FL	*485.00 FL
27	1		*FRONT WHEEL HUB	Damaged	241.65 FL	*241.65 FL
28	1		*FRONT WHEEL BEARING	Damaged	190.60 FL	*190.60 FL
29	1		*FRONT ANTI ROLL BAR	Not Necessary	441.50 FL	*- FL
30	1		*FRONT ANTI ROLL BAR LINK	Not Necessary	126.30 FL	*- FL
31	1		*FRONT HEADLAMP	Cracked	927.00 FL	*927.00 FL
32	1		*FRONT HEADLAMP CHROME MOULDING	Necessary	181.90 FL	*181.90 FL
33	1		*AIR CLEANER RESONATOR	Deformed	280.90 FL	*280.90 FL
34	1		*AIR CLEANER INTAKE DUCT	Deformed	190.90 FL	*190.90 FL
35	1		*REAR DOOR	Dented	1,257.60 FL	*1,257.60 FL
36	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	141.20 FL	*- FL
37	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	182.55 FL	*- FL
38	1		*REAR DOOR GLASS REGULATOR	Not Necessary	280.60 FL	*- FL
39	1		*REAR DOOR 1/4 GLASS RUBBER	Not Necessary	86.90 FL	*- FL
40	1		*REAR DOOR W/STRIP	Not Necessary	161.80 FL	*- FL
41	1		*REAR DOOR INNER LOCK	Not Necessary	361.90 FL	*- FL
42	1		*REAR DOOR INSULATION	Not Necessary	130.20 FL	*- FL
43	1		*REAR DOOR CHECKER	Not Necessary	89.95 FL	*- FL
44	2		*REAR DOOR HINGES	Not Necessary	211.00 FL	*- FL
45	1		*REAR FENDER-LH	Repair	1,089.90 FL	*- FL
46	1		*REAR BUMPER	Repair	561.90 FL	*- FL
47	1		*REAR WHEEL HUB BEARING-LH	Not Necessary	761.90 FL	*- FL
48	1		*REAR SHOCK ABSORBER-LH	Not Necessary	399.60 FL	*- FL
49	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
50	1		*REAR SPORT WHEEL-LH	Cut	550.00 FS	*400.00 FS
51	1		*REAR TYRE-LH	Not Necessary	350.00 FS	*- FS
52	1		*FRONT SPORT WHEEL-LH	Cut	550.00 FS	*400.00 FS
53	1		*FRONT TYRE-LH	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
55	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*30.00 FS
56	1		*SET FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,860.97	8,690.88
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,428.99	1,927.72
Total Parts (\$\$)	15,431.98	6,763.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	80.00	30.00
2	TO CHECK FRONT UNDERCARRIAGE	New	350.00	220.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
4	TO RESPRAY UNDERCOATING	New	180.00	50.00
5	TO RESPRAY PAINTING AND ETC	New	1,800.00	1,200.00
6	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS	New	1,800.00	800.00
Gross Labour Cost (\$\$)			4,330.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >