

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20014370/ETF3N2
Date: 14/01/2021

REFERENCE

Insured/Claimant: KHAIRUL AZMEEL BIN KAHAR Policy No:
Date of Loss: 23/12/2020 Nature of Claim: OD Claim No: 7201444317SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW5634A
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH694654
Reg. Date: 22/02/2018 (Man. Year: 2017) Chassis No: KNAFZ411MJ5764432
Colour: Grey Odometer: 110881 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,347.00	3,249.60	2,097.40	39.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,130.00	1,150.00	50.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,627.00	4,379.60	3,247.40	42.58
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	7,327.00	4,079.60	3,247.40	44.32
+ GST 7.00/7.00% (S\$)	512.89	285.57	227.32	44.32
Nett Amount (S\$)	7,839.89	4,365.17	3,474.72	44.32

INSPECTION

Date of Assignment: 23/12/2020
Date Inspected: 23/12/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER	Dented	633.00 F	*633.00 FL
2	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	18.00 F	*18.00 FL
3	1		*GRILLE ASSY-RADIATOR	Broken	328.00 F	*328.00 FL
4	1		*GARNISH-RADIATOR GRILLE-UPR	Not Necessary	54.00 F	*- FL
5	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	91.00 F	*- FL
6	1		*DUCT ASSY-AIR CURTAIN,RH	Not Necessary	6.00 F	*- FL
7	1		*AIR DUCT-FR BUMPER,RH	Not Necessary	33.00 F	*- FL
8	1		*LAMP ASSY-FRONT FOG,RH	Not Necessary	241.00 F	*- FL
9	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
10	1		*RAIL ASSY-FR BUMPER	Bent	496.00 F	*496.00 FL
11	1		*BRACKET-FR BUMPER SIDE MTG,RH	Not Necessary	13.00 F	*- FL
12	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	177.00 F	*- FL
13	1		*LAMP ASSY-HEAD,RH	Broken	2,209.00 F	*2,209.00 FL
14	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 F	*- FL
15	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
16	1		*WIRING HARNESS- FR BUMPER	Broken	237.00 F	*237.00 FL
			(Supplementary)			
17	1		*ORNAMENT- KIA NO. 115	Necessary	32.00 F	*32.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,347.00	4,057.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	807.40
Total Parts (\$\$)	5,347.00	3,249.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER,FRT SUPPORT PANEL,REPAIR FRT FENDER RH	New	1,200.00	400.00
2	SPRAY PAINT FOR FRT BUMPER,FRT FENDER RH	New	700.00	350.00
3	FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
4	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	REMOVE & INSTALL FRONT AIRDAM (Supplementary)	New	80.00	80.00
7	APPLY SEALANT FOR FRONT AIRDAM (Supplementary)	New	40.00	40.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			2,280.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >