

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20014374/R1QD3Q2

**Date:** 25/01/2021

### REFERENCE

|   |                               |                            |
|---|-------------------------------|----------------------------|
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: DMPCNSA00003832001 |                            |
| Claimant Vehicle No : SGM4977D                                  | Insured Vehicle No : S5337CD  |                            |
| Date of Loss: 20/12/2020  | Nature of Claim: TP           | Claim No: SNM20D204957/C02 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SGM4977D                     |             |                   |
| Make & Model:               | LEXUS GS300, 3.0 (A)         | Engine No:  | 3GR0189089        |
| Reg. Date:                  | 20/10/2006 (Man. Year: 2006) | Chassis No: | JTHBH96S805047759 |
| Colour:                     | Blue                         | Odometer:   | 153354 km         |
| Engine Capacity:            | 2995 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price   |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/50 ZR17   | Rear Tyre Size:  | 225/50 ZR17   |
| Front Left Side:  | Habilead 6 mm | Rear Left Side:  | Habilead 6 mm |
| Front Right Side: | Habilead 6 mm | Rear Right Side: | Habilead 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                            | Repairer's      | Adjuster's      | Difference      | Diff %       |
|---|-----------------|-----------------|-----------------|--------------|
| Parts                                     | 3,436.50        | 2,158.60        | 1,277.90        | 37.19        |
| Miscellaneous Items                       | 0.00            | 0.00            | 0.00            |              |
| Labour                                    | 1,600.00        | 1,300.00        | 300.00          | 18.75        |
| Paintwork Labour                          | 0.00            | 0.00            | 0.00            |              |
| Towing                                    | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>5,036.50</b> | <b>3,458.60</b> | <b>1,577.90</b> | <b>31.33</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                 | <b>2,750.00</b> |                 |              |
| <b>(\$\$)</b>                             | 5,036.50        | 2,750.00        | 2,286.50        | 45.40        |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 352.56          | 192.50          | 160.06          | 45.40        |
| <b>Nett Amount (\$\$)</b>                 | <b>5,389.06</b> | <b>2,942.50</b> | <b>2,446.56</b> | <b>45.40</b> |

### INSPECTION

Date of Assignment: 23/12/2020

Date Inspected: 28/12/2020 Inspected At:

Wah Hong Motors & Credit Pte Ltd  
(HQ)  
38 Toh Guan Road East, #01-57,  
Enterprise Hub  
Singapore 608581

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 22 Jan 2021)         |
| <b>Parts:</b>        | 143  | LEXUS GS300 3.0 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SGM4977D)  |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition   | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------|-------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                        | Deformed    | 979.00 FL  | *845.00 FL |
| 2   | 1   |          | *REAR REINFORCEMENT                 | Bent        | 579.00 FL  | *507.00 FL |
| 3   | 1   |          | *BOOT LID LOCK                      | Cut         | 781.00 FL  | *408.00 FL |
| 4   | 1   |          | *REAR BUMPER SPONGE                 | Serviceable | 190.00 FL  | *- FL      |
| 5   | 2   |          | *REAR BUMPER SIDE RETAINER LH/RH    | Serviceable | 362.00 FL  | *- FL      |
| 6   | 1   |          | *REAR BUMPER SCREW COVER GARNISH RH | Missing     | 44.00 FL   | *44.00 FL  |
| 7   | 1   |          | *REAR BUMPER CLIPS                  | Necessary   | 35.00 FS   | *35.00 FS  |
| 8   | 2   |          | *REAR REVERSE SENSOR                | Cracked     | 760.00 FS  | *500.00 FS |
| 9   | 1   |          | *BOOT LID (NPA)                     | Repair      | 0.00 FL    | *- FL      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>3,730.00</b> | <b>2,339.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (S\$)</b> | 293.50          | 180.40          |
| <b>Total Parts (S\$)</b>                                  | <b>3,436.50</b> | <b>2,158.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |  |          |                 |                 |
| 1                               | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS (END PANEL REPAIR) | New      | 800.00          | 600.00          |
| 2                               | TO SUPPLY PAINT MATERIALS ,EXPANDABLE & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED  | New      | 600.00          | 600.00          |
| 3                               | TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK ALL ELECTRICAL & COMPONENT FOR PROPER FUNCTION  | New      | 60.00           | 40.00           |
| 4                               | TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS   | New      | 40.00           | 0.00            |
| 5                               | TO REMOVE AND REFIT/REPLACE REVERSE SENSOR   | New      | 100.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>1,600.00</b> | <b>1,300.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >