

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20014375/AQF3Q2**Date:** 18/03/2021**REFERENCE**

Insured/Claimant: LIM TENG TIN ROCHELLE(LIN TINGZHEN) Policy No: 1900080799

Date of Loss: 20/12/2020

Nature of Claim: OD

Claim No: 9989575761SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLX816U**

Make & Model: AUDI Q2, 1.4 (A)

Engine No: CHZA92540

Reg. Date: 28/03/2019 (Man. Year: 2018)

Chassis No: WAUZZZGA5KA001834

Colour: Orange

Odometer: 16319 km

Engine Capacity: 999 cc

Market Value/New Car Price: S\$105,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,430.00	1,999.68	8,430.32	80.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,852.00	1,242.00	4,610.00	78.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,282.00	3,241.68	13,040.32	80.09
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	15,482.00	2,441.68	13,040.32	84.23
+ GST 7.00/7.00% (S\$)	1,083.74	170.92	912.82	84.23
Nett Amount (S\$)	16,565.74	2,612.60	13,953.14	84.23

INSPECTION

Date of Assignment: 23/12/2020

Date Inspected: 23/12/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,854.00 FS	*1,482.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	343.00 FS	*- FS
3	2		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	167.00 FS	*- FS
4	1		*FRONT BUMPER END CAP-LH	Not Necessary	34.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	296.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	154.00 FS	*- FS
7	1		*WHEEL SPOILER-LH	Not Necessary	34.00 FS	*- FS
8	1		*FRONT BUMPER ADAPTER-LH	Not Necessary	35.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	35.00 FS	*- FS
10	1		*FRONT FENDER-LH	Not Necessary	1,134.00 FS	*- FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
12	1		*FRONT FENDER BRACKET-INNER	Not Necessary	47.00 FS	*- FS
13	1		*FRONT FENDER BRACKET-OUTER	Not Necessary	16.00 FS	*- FS
14	1		*FRONT FENDER BRACE-LH	Not Necessary	37.00 FS	*- FS
15	1		*WHEEL HOUSING LINER-LH	Not Necessary	194.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
17	1		*HEADLIGHT MOUNTING-LH	Not Necessary	117.00 FS	*- FS
18	1		*LED HEADLIGHT-LH	Not Necessary	4,859.00 FS	*- FS
19	1		*LIFT CYLINDER-LH	Not Necessary	141.00 FS	*- FS
20	2		*FRONT WHEEL COVER-LH/RH	O/s Necessary/N/s Cut	636.00 FS	*508.80 FS
21	1		*SUNDRIES	Necessary	200.00 FS	*8.88 FS
					Total Parts (\$\$)	10,430.00 1,999.68

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,852.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >