LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20014376/R1TD3E2

Date: 05/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070035031

Claimant Vehicle No: YN2752E Insured Vehicle No: GBJ4095Z

Date of Loss: 12/12/2020 Nature of Claim: TP Claim No: 8820751649SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN2752E

Make & Model: HINO XZU710R-HKFMS3, 4.0 D (M) Engine No: N04CUV10679

Reg. Date: 16/01/2012 (Man. Year: 2011) Chassis No: JHHUCP3HX0K001693

Colour: White Odometer: 360310 km

Engine Capacity: 4009 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16 (D)
Front Left Side: OHTSU 7 mm Rear Left Side: OHTSU 7/7 mm
Front Right Side: OHTSU 7 mm Rear Right Side: OHTSU 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment: 23/12/2020

Ngee Ngee Motor

Block K, No. 22 Pandan Road

Singapore 128240

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

Inspected At:

24/12/2020

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR END PANEL (WOODEN)	Cracked	0.00 F	*- F
2	1	*TAILGATE	Bent	0.00 F	*- F
F=Fr	anchise part.		Total Parts (S\$)	0.00	0.00
		Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >