

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20014379/R1QD3Q2

**Date:** 18/02/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00127812002
<b>Claimant Vehicle No :</b>	SME9971H	<b>Insured Vehicle No :</b>	SKG5145R
Date of Loss:	19/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204981/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME9971H	Engine No:	B4204T182748835
Make & Model:	VOLVO XC40, 2.0 T5 R-DESIGN (A)	Chassis No:	YV1XZ16ACK2075715
Reg. Date:	25/10/2018 (Man. Year: 2018)	Odometer:	25705 km
Colour:	White		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	235/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,975.66	7,895.94	5,079.72	39.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,325.00	4,325.00	7,000.00	61.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>24,300.66</b>	<b>12,220.94</b>	<b>12,079.72</b>	<b>49.71</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,701.05</b>	<b>855.47</b>	<b>845.58</b>	<b>49.71</b>
<b>Nett Amount (S\$)</b>	<b>26,001.71</b>	<b>13,076.41</b>	<b>12,925.30</b>	<b>49.71</b>

### INSPECTION

Date of Assignment:	23/12/2020	
Date Inspected:	11/01/2021 Inspected At:	Wearnes Automotive Pte Ltd (Leng Kee)
		28 Leng Kee Road
		Singapore 159105
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2021)
<b>Parts:</b>	M1-SUV	VOLVO XC40 2.0 T5 R-DESIGN (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME9971H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR AL	Deformed	1,353.10 FS	*1,217.79 FS
2	1		*BUMPER PAD REAR LH A	Serviceable	638.70 FS	*- FS
3	1		*BUMPER PAD REAR RH A	Serviceable	638.70 FS	*- FS
4	1		*BUMPER BRACKET REAR	Serviceable	44.50 FS	*- FS
5	1		*BUMPER BRACKET REAR	Serviceable	44.50 FS	*- FS
6	1		*TOW COVER REAR XC40	Scratched	77.70 FS	*69.93 FS
7	1		*BUMPER RAIL (BEAN) R	Bent	1,403.90 FS	*1,263.51 FS
8	1		*BUMPER REFLECTOR RH	Missing	86.40 FS	*77.76 FS
9	1		*BUMPER REFLECTOR LH	Cracked	86.40 FS	*77.76 FS
10	1		*PROTECTING PLATE REA	Bent	466.00 FS	*419.40 FS
11	1		*PROTECTING PLATE REA	Bent	675.30 FS	*607.77 FS
12	1		*END PIPE FRAME LH R	Serviceable	388.50 FS	*- FS
13	1		*END PIPE FRAME RH R	Bent	388.50 FS	*349.65 FS
14	1		*GUIDE MOULDING REAR	Serviceable	78.00 FS	*- FS
15	1		*CROSS MEMBER REAR XC	Serviceable	233.70 FS	*- FS
16	1		*REAR SECTION INNER X	Serviceable	760.10 FS	*- FS
17	1		*PARK ASSIST SENSOR R	Not Working	81.50 FS	*73.35 FS
18	1		*SILENCER	Bent	754.70 FS	*679.23 FS
19	1		*END PIPE LH ALL XC40	Bent	736.80 FS	*663.12 FS
20	1		*END PIPE RH ALL XC40	Bent	736.80 FS	*663.12 FS
21	1		*EXHAUST CLAMP 60MM S	Necessary	132.70 FS	*119.43 FS
22	1		*HEAT SHIELD REAR XC4	Bent	178.70 FS	*160.83 FS
23	10		*BLIND RIVET 4.0 *21 P	Not Necessary	32.00 FS	*- FS
24	10		*BUMPER EXPANSION PLU	Serviceable	75.00 FS	*- FS
25	10		*CLIP WHITE V40 SV90	Necessary	166.00 FS	*149.40 FS
26	1		*BUMPER INSTALLING MT	Necessary	87.70 FS	*78.93 FS
27	4		*RUST INHIBITING FLUI	Not Necessary	312.00 FS	*- FS
28	1		*ADHESIVE TUBE CHEMIC	Not Necessary	725.00 FS	*- FS
29	1		**D* WELDING PRIMER	Not Necessary	367.80 FS	*- FS
30	1		*REAR NUMBER PLATE	Bent	60.00 FS	*60.00 FS
31	1		*END PIPE BRACKET LH	Necessary	42.12 FS	*42.12 FS
32	1		*END PIPE BRACKET RH	Necessary	42.12 FS	*42.12 FS
33	1		*EMBLEM VOLVO REAR	Necessary	87.03 FS	*87.03 FS
34	1		*EMBLEM T5 XC60 S80	Necessary	83.25 FS	*83.25 FS
35	1		*END PIPE FRAME LH R	Bent	349.65 FS	*349.65 FS
36	1		*FMD SENSOR XC40 18	Not Working	313.47 FS	*313.47 FS
37	1		*EMBLEM XC40 18	Necessary	99.36 FS	*99.36 FS
38	1		*CABLE HARNESS BUMPER	Cut	147.96 FS	*147.96 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>12,975.66</b>	<b>7,895.94</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE TAILGATE,REAR BUMP REAR SPOILER,BUMPER PADS,END PANEL,SKID PLATE,EMBLEMS,SENSORS,ETC	New	4,800.00	1,600.00
2	TO PUTTY AND SPRAY PAINT ON TAILGATE,LHS AND RHS BUMPER PADS,END PANEL,ETC	New	2,800.00	1,400.00
3	TO REPLACE EXHAUST SYSTEM	New	1,600.00	800.00
4	TO REMOVE AND INSTALL REAR BOOT COMPARTMENT PARTS	New	1,600.00	0.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	525.00	525.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,325.00</b>	<b>4,325.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >