

CVR Accident Photos






VEHICLE DETAIL

Vehicle No	QX1093Y / SLA2105X	Date Of accident	
Date Booked In		Date of Submission	

REPAIR DESCRIPTIONS

<ol style="list-style-type: none"> 1. Panel Beating for Rear LH Door damaged area (Pic 1-2) 2. Putty & Spray Paint for Rear LH Door repaired area (Pic 1-2) 3. Putty & Spray Paint for LHS Skirting (Pic 3-4)
--

PHOTOS OF DAMAGED PARTS

Rear LH Door Dented & Scratched (Pic 1) 	Rear LH Door Dented & Scratched (Pic 2) 
LHS Skirting Scratched (Pic 3) 	LHS Skirting Scratched (Pic 4) 
Odometer Reading (Pic 5) 	QX1093Y / SLA2105X (Pic 6) 